

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT124/20252/4nh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: VP 9282M

at Workshop m/s

hupian Huaf

of

Insured:

GAG 3110K

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$58/c.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

LTA 811233

Date / Time

Action / Instruction

Dep 10/1

20-1-25 2/5 \$16,000 inform schui
(Red. \$ 13062.58. 441.)

Veh No:

VP9282M

Yr Regn:

31/07/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Car

Make:

HINO XZU710R

c.c

4009

Colour

multi colour

A/C:

Insured / Std / NI / NA

Sp. Reading

274634

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JH HUCV1H50K027254

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65-R16

R:

1060

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodride

Front

6

Rear

6/6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

13/1/24

D.O.I.

20/1/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt n/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	158D
Vehicle Details	
Vehicle No.:	YP9282M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Dec 2024
Vehicle Make:	HINO
Vehicle Model:	XZU710R 14FT WIDE CAB 7T
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	N04CVV10321
Chassis No.:	JHHUCV1H50K027254
Maximum Power Output:	-
Open Market Value:	\$36,547.00
Original Registration Date:	31 Jul 2018
First Registration Date:	31 Jul 2018
Transfer Count:	1
Actual ARF Paid:	\$1,828.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,889.00
COE Rebate Amount:	\$11,233.00
Total Rebate Amount:	\$11,233.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Dec 2024

OK

HUP LIAN HUAT ENGINEERING WORKS

Blk 2 Defu South Street 1 #04-01
Defu Industrial City, Singapore 533755
TEL : 6282 3336 FAX : 6289 3336 Email : mahlian@singnet.com.sg

no + Approval
as
means
20/12/24
2/4 16,000
24/12/24
7 days

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00
Springleaf Tower, Singapore 079909
ATTN : Motor Claim Department

Claim Type : Third Party
Accident Date : 13/12/2024
TP Vehicle No : GBG3110K
Wee Guan Engineering Pte Ltd

ESTIMATE No : ES2024002
DATE : 06/01/2025
Policy No : 2024-V5022794-VCV
Veh Reg No : YP9282M
Make & Model : HINO XZU710R 14F WIDE CAB 7T
Chassis No : JHHUCV1H50K027254
Engine No : N04CVV10321
Reg Date : 31/07/2018

ESTIMATE OF VEHICLE NO : YP9282M

Description	Qty	List Price
List Price		
1 Front Bumper	1	1,414.46 ✓
2 Front Bumper bracket LH/RH	1	457.97 ✗
3 Front Bumper Fog Lamp LH	1	338.90 ✓
4 Front Grille Lower (Green)	1	1,547.47 ✓
5 Front Grille Upper (Sliver)	1	558.00 ✗
6 Front Panel	1	3,530.56 ✓
7 Front Corner Panel LH	1	709.46 ✓
8 Front Corner Panel Seal Plate LH	1	172.55 ✓
9 Front Wipers	2	218.00 ✗
10 Front Panel inner Panel	1	2,257.90 ✓
11 Front Headlamp LH	1	1,558.90 ✓
12 Front Headlamp Bracket LH	1	233.00 ✗
13 Front Door LH	1	3,202.03 ✓
14 Front Door Hinge	2	212.00 ✓
15 Front Door Signal LH	1	118.00 ✗
16 Front Step Garnish LH	1	333.90 ✓
17 Front Step Garnish Reflector LH	1	108.00 ✗
18 Front Dashboard Upper (Black)	1	3,331.90 ✓
19 Condenser	1	1,778.90 ✓
20 Front Left mirror Stand	1	545.90 ✓
21 Front Left mirror (Round)	1	210.00 ✗
22 Front Left Mirror (Bie)	1	289.00 ✓
23 Front door pillar LH	1	2,225.90 ✓
24 Front Panel Sticker (300)	1	111.00 ✗
25 Front panel Sticker (HINO)	1	216.94 ✗
		25,680.64
	Less 10%	2,568.06
		23,112.58

Net Price

26 Commercial Sticker Front Panel	1	450.00 250
27 Commercial Sticker Front Door	1	400.00 250
28 Front Panel Seal	1	120.00 ✗
29 Front Inner Panel Seal	1	120.00 ✗
30 Front Dashboard Upper Clips	1set	80.00 ✗

HUP LIAN HUAT ENGINEERING WORKS

Blk 2 Defu South Street 1 #04-01
Defu Industrial City, Singapore 533755
TEL : 6282 3336 FAX : 6289 3336 Email : mahlian@singnet.com.sg

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00
Springleaf Tower, Singapore 079909
ATTN : Motor Claim Department

Claim Type : Third Party
Accident Date : 13/12/2024
TP Vehicle No : GBG3110K
Wee Guan Engineering Pte Ltd

ESTIMATE No : ES2024002
DATE : 06/01/2025
Policy No : 2024-V5022794-VCV
Veh Reg No : YP9282M
Make & Model : HINO XZU710R 14F WIDE CAB 7T
Chassis No : JHHUCV1H50K027254
Engine No : N04CVV10321
Reg Date : 31/07/2018

ESTIMATE OF VEHICLE NO : YP9282M

Description	Qty	List Price	
31 Front Dashboard Lower Clips	1set	80.00	1,250.00
			1,250.00
Labour			
32 Labour to renew & dismantle & cut & Weld all above parts		1,800.00	1,800.00
33 Labour to perform wire checking		150.00	150.00
34 Labour to remove and refit front door, transfer parts		150.00	150.00
35 Labour to remove and reift front windscreen		200.00	200.00
36 Labour to remove Front dashboard upper & lower		600.00	600.00
37 To spray & painting accident affected area(3 tone colors)		1,800.00	1,800.00
		4,700.00	4,700.00

Total \$ 29,062.58
Add GST 9% \$ 2,615.63
TOTAL AMOUNT \$ 31,678.21

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

P-18134-65
102
17221-19
500
2480
20201-19
202
16000