



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24120254/Knp3e2
16 RAFFLES QUAY	Date:	24/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4497H	Veh. Inspected	SCP 7561G
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24011026MFCT	Excess	\$0.00
Assign From	JASON	Assign Date	17/12/2024

### 2. Vehicle Details

Make & Model	TOYOTA ALTIS (A)	C.C	1598
Engine No.	3ZZ4578340	Year of Reg.	30/06/2006
Chassis No.	MR053ZEC107122695	Colour	METALLIC GOLD
Odometer	408178 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	HICITY	9
L/H Front Tyre	195/65R15	HICITY	9
R/H Rear Tyre	195/65R15	KAPSEN	8
L/H Rear Tyre	195/65R15	KAPSEN	8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	14/12/2024	Inspection Date	19/12/2024
Survey held at	CHOON HOCK AUTOCARE PTE LTD - BLK 176 SIN MING DRIVE #05-05 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days