

CHOON HOCK MOTOR TRADING CO

18 December 2024

Not Asstained
 11 Pmp & 3600p
 Repair After Pains
 6 days

ESTIMATE REPAIR BILL ON SCP7561G TOYOTA COROLLA ALTIS 1.6E VVTI AUTO

1 pce boot lid emblem	Ne \$ 26.00	✓
1 pce boot lid "COROLLA" plate	ne \$ 28.00	✓
1 pce boot lid "ALTIS" plate	ne \$ 35.00	✓
1 pce boot lid "1.6E" plate	ne \$ 44.00	✓
1 pce boot lid "VVDTi" plate	ne \$ 41.00	✓
1 pce boot rubber	3L \$ 188.60	X
1 pce rear lamps assy RH	Bj \$ 328.00	✓
1 pce rear lamp lower panels RH	Bj \$ 89.00	✓
1 pce rear panel	Bj \$ 722.40	✓
1 pce rear panel inner garnish	Pd \$ 168.00	X
1 pce rear bumper fascia	CM \$ 685.00	✓
1 pce rear bumper brackets RH	Bj \$ 48.00	✓
1 pce rear bumper side retainers RH	Di \$ 29.00	✓
1 set rear windscreen moulding	Ne \$ 180.00	✓
1 pce rear fender RH	Bj \$ 950.00	X
	\$3,562.00	
less 25%	\$ 890.50	
	\$2,671.50	

SNETT/LABOUR

1 pce rear panel sealant	Ne \$ 60.00	305N
1 set rear panel inner garnish clips	ne \$ 14.00	X
1 set rear bumper clips	ne \$ 35.00	✓
1 set reverse sensors	Se \$ 220.00	X
1 set rear windscreen sealant	ne \$ 60.00	X
Remove and refit rear windscreen	Ne \$ 200.00	X
Remove reverse sensors, refit	\$ 120.00	501
Wirings	\$ 60.00	201
Panel beating	\$ 1,200.00	1000
Spray painting	\$ 1,200.00	8001
Rustproof	\$ 120.00	601
Total amount :	\$5,960.50	NETT

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L

Tel: (65) 64530778 Email: choonhockmotor@gmail.com

Signature:
 Date: