7/17/24, 4:29 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24070023/EVP3M4

Date: 17/07/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MZC03915 **Claimant Vehicle**

SHD7088K Insured Vehicle No: YQ8069P No:

Date of Loss: 29/06/2024 Nature of Claim: TP Claim No: M2403619

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD7088K Reg No:

TOYOTA PRIUS HYBRID, 1.8 CVT (A) Make & Model: Engine No: 2ZRR959645

11/11/2016 (Man. Year: 2016) JTDKB3FU803536904 Reg. Date: Chassis No:

Colour: Blue Odometer: 169025 km

Engine Capacity: 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes **Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes Nο Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
2,365.91	1,901.03	464.88	19.65
12.00	12.00	0.00	0.00
2,170.00	1,990.00	180.00	8.29
0.00	0.00	0.00	
0.00	0.00	0.00	
\$) 4,547.91	3,903.03	644.88	14.18
\$)	3,100.00		
\$) 4,547.91	3,100.00	1,447.91	31.84
\$) 409.31	279.00	130.31	31.84
\$) 4,957.22	3,379.00	1,578.22	31.84
	2,365.91 12.00 2,170.00 0.00 0.00 \$) 4,547.91 \$) \$) 4,547.91 \$) 409.31	2,365.91 1,901.03 12.00 12.00 2,170.00 1,990.00 0.00 0.00 \$) 4,547.91 3,903.03 \$) 4,547.91 3,100.00 \$) 4,547.91 3,100.00 \$) 4,931 279.00	2,365.91 1,901.03 464.88 12.00 12.00 0.00 2,170.00 1,990.00 180.00 0.00 0.00 0.00 0.00 0.00 0.00 \$\$\) 4,547.91 3,903.03 644.88 \$\$\) 3,100.00 \$\$\) 4,547.91 3,100.00 1,447.91 \$\$\) 409.31 279.00 130.31

INSPECTION

Date of Assignment: 01/07/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 01/07/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2024)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD7088K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR ASSY	Dented	1,258.30 FL	*1,258.30 FL
2	1		*REAR RH FENDER ASSY	Dented	992.04 FL	*992.04 FL
3	1		*REAR BUMPER ASSY	Repair	503.04 FL	*- FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	94.80 FL	*- FL
6	1		*REAR WHEEL RIM CAP	Cut	177.70 FL	*177.70 FL
7	1	part. L=ListIte	*REAR DOOR APPS LOGO	Necessary	80.00 F	*80.00 F
1 -1 10	ancinse	part. L-Listite	IIDISC.	Sub Total (S\$)	3,127.88	2,508.04
			- List Item Discount or	n L Items 25.00/25.00% (S\$)	761.97	607.01
				Total Parts (S\$)	2,365.91	1,901.03
			Report was unsubmitted o	during this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		12.00	12.00
	Sub Total (S\$)	12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,200.00	1,140.00
2	SPRAYPAINT	New	800.00	800.00
3	TUFF KOTE	New	50.00	20.00
4	TRANSFER DOOR PARTS	New	120.00	30.00
		Gross Labour Cost (S\$)	2,170.00	1,990.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.