



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24120258/Tqp3m4(N)
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	09/05/2025
HEMMANT ROADSINGAPORE 438675			
ATTN: LAI PENG CHONG		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 527U	Veh. Inspected	SNA 6585T
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/064 (LK)	Excess (\$)	0.00
Assign From	LAI PENGCHONG	Assign Date	17/12/2024
2. Vehicle Particulars & Condition			
Make & Model	BMW 216I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	WBA2X920407H97821	Colour	SILVER
Odometer	37074 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R17	BRIDGESTONE	6 mm
L/H Front Tyre	205/55R17	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55R17	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/12/2024	Inspection Date	16/04/2025
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	