



Final Report

Estimate No. : **b1 72115**
Date Estimated : **13/12/2024**
Prepared By : **Chua Kee Sin**

Page No. :

- ESTIMATE REPAIR FOR -

Hong Ching Chung
37 CHEMPAKA AVENUE

SINGAPORE 349650

- ACCOUNT - 86463

SPF Accident Claims Section
Automotive Engr & Mgt Div
Police Logistic Department
Blk 8 Old Police Academy 298333
No.1 Mount Pleasant Rd#02-12

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SNA6585T	WBA2X920407H97821	01/07/2021	216i Active Tourer	34992

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear RH door include making good the rear bumper panel, rear RH fender, RH side skirting, RH roof frame, both RH door handles and carrying out other necessary repairs caused by the accident	2,975.00		2,975.00	
To spray paint rear bumper, rear RH fender, rear RH door, RH side skirting, RH roof frame and both RH door handles	4,147.00		4,147.00	
To carry out body cavity preservation (x1) (Per panel)	118.00		118.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (x1)	531.00		531.00	
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (x1)	531.00		531.00	
To replace rear RH wheel rim include balancing (x1)	94.00		94.00	
Sundries	150.00		150.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 7.5X17 DOUBLE SPK 549	968.30	1.00	0.00	968.30
RR RH DOOR	1,356.25	1.00	0.00	1,356.25

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W





Final Report

SUPPLEMENTARY ITEMS

Total Labour :	8,723.00
Total Parts :	2,324.55
Total Labour & Parts (before GST) :	11,047.55
Deduction for Excess :	
Total Repair Costs less Excess:	11,047.55
GST @9%:	994.28
Grand Total :	12,041.83

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W