

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | Affiliated to Federation Internation | onale Des Experts En | Automobile | |
|--|--|---|----------------------|-----------------------|--|
| MS | LIBERTY INSURAN | | Ref: | CS/LIP24120259/Enh3e2 | |
| | ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 | | Date: | 24/12/2024 | |
| | ON ONE ONE OFFICE | | Code: | LIP | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | YQ 8314G | Veh. Inspected | GBH 5434H | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | AVS24/3879 | Excess | \$0.00 | |
| | Assign From | - | Assign Date | 17/12/2024 | |
| 2. Vehicle Details | | | | | |
| | Make & Model | MITSUBISHI L200 | C.C | 2477 | |
| | Engine No. | 4N15UCP2578 | Year of Reg. | 06/07/2018 | |
| | Chassis No. | MMCJJKL20JH012334 | Colour | WHITE | |
| | Odometer | 78356 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | FAIR | |
| | Modification(s) | RIMS: SPORTS RIM | | | |
| 3. | | Conditions of Tyres | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 205 R16C | GT RADIAL | 5 | |
| | L/H Front Tyre | 205 R16C | GT RADIAL | 5 | |
| | R/H Rear Tyre | 205 R16C | GT RADIAL | 5 | |
| | L/H Rear Tyre | 205 R16C | GT RADIAL | 5 | |
| 4. | 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 07/12/2024 | Inspection Date | 18/12/2024 | |
| | Survey held at LIU'S BROTHER AUTO WORK SHOP | | | | |
| | | 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT | | | |
| | | SINGAPORE 417883 | | | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | |
| 5D. | | | | | |