Not Notherisal 11 Ly & 1850h Resurry After Pary

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number: SLG 8577X

Date: 11.12.24

S/N	Parts Description	Unit Price Amt	
2 3 5 6 7 8 9 10 11	Rear tailgate Rear tailgate emblem Rear tailgate Prius emblem Rear tailgate Hybrid emblem Rear tailgate rubber Rear bumper assy Rear bumper reinforcement Rear bumper retainer X 2 Rear bumper lower Rear bumper lower Rear end panel Rear end panel top garnish Rear panel sensor	STATE OF THE PROPERTY OF THE P	\$288.90 × \$485.60 \$378.30 \$265.20 ×
2	Special Nett 1 Rer bumper clips 2 Rear windscreen sealant 3 Rear No.plate	Na Na Na	\$50.00 \$60.00 X \$80.00 X

Labour

1 To remove and refit damaged parts, cut/weld damaged areas.		\$800.00	3501
2 To spray paint on affected areas.		\$800.00	400/
3 Check wiring		\$50.00	15/
4 Tuff coating	NN	\$120.00	×
5 To remove and refit rear windscreen	an	\$120.00	X
6 To remove and refit rear ganishes etc.	nn	\$180.00	X

\$2,070.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: