



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 7493D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR GATE	NOT NECESSARY	2,534.00	-
1	REAR GATE HINGES LH	NOT NECESSARY	150.00	-
1	REAR GATE HINGES RH	NOT NECESSARY	150.00	-
1	REAR GATE SIDE LOCK LH	NOT NECESSARY	168.00	-
1	REAR GATE SIDE LOCK RH	NOT NECESSARY	168.00	-
1	REAR GATE SAFETY LOCK	NOT NECESSARY	160.00	-
2	REAR GATE STOPPER RUBBER	NOT NECESSARY	150.00	-
2	REAR GATE STOPPER RUBBER BRACKET	NOT NECESSARY	220.00	-
1	REAR LAMP LH	NOT NECESSARY	399.60	-
1	REAR LAMP RH	NOT NECESSARY	399.60	-
1	END PANEL	TO REPAIR SEE LABOUR	1,100.00	-
1	REAR FLOOR PANEL	NOT NECESSARY	2,540.00	-
	LESS 20% DISCOUNT		-1,627.84	-
			6,511.36	-
1	REAR STEP PANEL (SN)	DENTED	658.00	500.00
1	REAR LOWER PANEL (SN)	DENTED	1,325.00	1,000.00
	LESS 20% DISCOUNT		-396.60	-
			1,586.40	1,500.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REFLECTIVE STICKERS (SN)	NECESSARY	200.00	150.00
1	STICKERS 60KM (SN)	NOT NECESSARY	50.00	-
1	STICKERS 21PAX (SN)	NOT NECESSARY	50.00	-
2	REAR NUMBER PLATE LAMP (SN)	NOT NECESSARY	230.00	-
1	REAR NUMBER PLATE (SN)	CUT	90.00	45.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	320.00	-
			940.00	195.00
<b><u>LABOUR</u></b>				
	CHECK WIRING AND LIGHTNING SYSTEM.		90.00	30.00

Report Ref No. CS/INC24120262/Enh3m4(N)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF END PANEL.		1,400.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,400.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	30.00
			2,990.00	860.00
<b>GRAND TOTAL</b>			<b>12,027.76</b>	<b>2,555.00</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,555.00</b>
--	--	--	--	-----------------

Report Ref No. CS/INC24120262/Enh3m4(N)

**TOTAL FOR SPARE PARTS: \$ 9,037.76 \$ 1,695.00**

**TOTAL FOR LABOUR : \$ 2,990.00 \$ 860.00**

**TOTAL REPAIR COST: \$12,027.76 \$ 2,555.00**

**CHEN TSUE YEE**

**Automotive Assessor**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**