



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24120264/Kvp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	24/12/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 257Z	Veh. Inspected	SJX 1550C
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/063 (CF)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	17/12/2024

2. Vehicle Details

Make & Model	B.M.W. IX3 (A)	C.C	-
Engine No.	HIDDEN	Year of Reg.	31/01/2023
Chassis No.	WBY42DU000S628835	Colour	METALLIC GREY
Odometer	44189 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R20	PIRELLI	7
L/H Front Tyre	245/45R20	PIRELLI	7
R/H Rear Tyre	275/40R20	PIRELLI	5
L/H Rear Tyre	275/40R20	PIRELLI	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2024	Inspection Date	18/12/2024
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #08-09 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days