

Estimated Cost of Repair

Attention To : **SPF Accident Claims Section**
 Automotive Engineering &
 Management Division
 1 Mount Pleasant Rd
 Block 8 Old Police Academy #02-
 12
 Singapore 298333

Claim Details

Case Ref. No. : TP/122024/7943
Date : 17-12-2024
Accident Date : 11-12-2024

Third Party Vehicle Details

Registration No : QX257Z

Vehicle Details

Make & Model : B.M.W. IX3 (BEV) ADPT HL SR
Chassis No : WBY42DU000S628835
Registration No : SJX1550C

| S/N | Description | Qty | Amount (\$S) |
|-----|-------------------------------|------|-------------------------|
| 1 | REAR BUMPER LH PARKING SENSOR | 1.00 | <i>See</i> \$345.30 ✓ |
| | | | \$345.30 |
| | | | Discount: -5% (\$17.27) |
| | | | \$328.03 |
| 2 | TO REPAIR DAMAGES | 1.00 | \$250.00 <i>1801</i> |
| 3 | TO SPRAY PAINTING | 1.00 | \$400.00 <i>3001</i> |

Subtotal w/o GST: \$978.03

Not Withheld
Payment After Repair
2 days
\$808.04

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Elaine Lee

This is a computer-generated document. No signature is required.