



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP MC
Xiao Chen.

LIAW CHIN MIN
83 TOH TUCK PLACE
SINGAPORE 596842

TAX INVOICE

Repair Code : CLM18487
Date in : 10/12/2024
Vehicle Num. : SJZ5525P
Model : HONDA CIVIC CRX M
Chassis/Eng# : JHMED93700S310032 D16A91605912

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>Dented</i>	1	1120.00	✓ 1,120.00
AIRCON CONDENSER ALUMINIUM PIPE	1	375.00	X 375.00
AIRCON CONDENSER DISCHARGE PIPE	1	382.00	X 382.00
ENGINE MOUNTING LH	1	200.00	X 200.00
ENGINE MOUNTING RH	1	300.00	X 300.00
FRONT BONNET <i>Dented</i>	1	1100.00	✓ 1,100.00
FRONT BONNET 'LOGO' EMBLEM <i>Nec</i>	1	50.00	✓ 50.00
FRONT BONNET HINGES L/R <i>Bent</i>	2	90.00	✓ 180.00
FRONT BONNET MECHANISM LOCK (LOWER) <i>Damaged</i>	1	179.00	✓ 179.00
FRONT BONNET MECHANISM LOCK (UPPER) <i>xwe nec</i>	1	100.00	X 100.00
FRONT BUMPER <i>Deformed</i>	1	1000.00	860 ✓ 1,000.00
FRONT BUMPER BLACK PROTECTOR <i>Nol nec</i>	1	160.00	X 160.00
FRONT BUMPER REINFORCEMENT <i>Nol nec</i>	1	400.00	X 400.00
FRONT BUMPER SIDE RETAINER L/R <i>Nol nec</i>	2	70.00	X 140.00
FRONT BUMPER SIGNAL LAMP L/R <i>cracked</i>	2	71.00	✓ 142.00
FRONT BUMPER TOP PANEL <i>Bent</i>	1	325.00	✓ 325.00
FRONT FENDER INNER SHIELD L/R <i>Nol nec</i>	2	190.00	X 380.00
FRONT FENDER L/R <i>Repair</i>	2	700.00	X 1,400.00

*** This is a computer-generated document which requires no signature. ***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@w51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIAW CHIN MIN
83 TOH TUCK PLACE
SINGAPORE 596842

Contact : 97455991 90109991

TAX INVOICE

Repair Code : CLM18487

Date in : 10/12/2024

Vehicle Num. : SJZ5525P

Model : HONDA CIVIC CRX M

Chassis/Eng# : JHMED93700S310032/D16A91605912

FRONT HEADLAMP L/R	cracked	2	1250.00	✓	2500.00
FRONT HORN	not nee	1	98.00	X	98.00
FRONT SIDE LAMP L/R	cracked	2	225.00	✓	450.00
FRONT SUPPORT PANEL	Buckled	1	700.00	✓	700.00
RADIATOR FAN BLADE	not nee	1	190.00	X	190.00
RADIATOR FAN COWLING	not nee	1	290.00	X	290.00
RADIATOR FAN MOTOR	not nee	1	460.00	X	460.00
REAR BUMPER	Distorted	1	1100.00	840 ✓	1100.00
REAR BUMPER BLACK PROTECTOR	not nee	1	250.00	X	250.00
REAR BUMPER INNER TOP BRACKET	Bent	1	325.00	✓	325.00
REAR BUMPER RH MUDFLAP	torn	1	290.00	✓	290.00
REAR BUMPER SIDE RETAINER L/R	RH cracked	2	90.00	90 ✓	180.00
REAR BUMPER TOP COVER	Deformed	1	480.00	350 ✓	480.00
REAR END PANEL	Dented	1	700.00	590 ✓	700.00
REAR RH FENDER	Distorted	1	1890.00	1350 ✓	1890.00
REAR RH FENDER GLASS WITH MOULDING	not nee	1	225.00	X	225.00
REAR RH FENDER INNER AIR VENT		1	100.00	X	100.00
REAR RH FENDER INNER PANEL	Repair	1	496.00	X	496.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIAW CHIN MIN
83 TOH TUCK PLACE
SINGAPORE 596842

Contact : 97455991 90109991

TAX INVOICE

Repair Code : CLM18487

Date in : 10/12/2024

Vehicle Num. : SJZ5525P

Model : HONDA CIVIC CRX M

Chassis/Eng# : JHMED93700S310032/D16A91605912

REAR RH FENDER INNER SHIELD	new	1	226.00	X	226.00
REAR RH FENDER INNER TRIM	Debond	1	600.00	370 ✓	600.00
REAR RH FENDER PROTECTOR	new	1	200.00	X	200.00
REAR RH KNUCKLE ARM	} Damaged	1	796.00	560 ✓	796.00
REAR RH KNUCKLE ARM BEARING		1	290.00	✓	290.00
REAR RH LOWER ARM	Bent	1	505.00	390 ✓	505.00
REAR RH STABILIZER LINK	Bent	1	190.00	✓	190.00
REAR RH TAILLAMP	cracked	1	700.00	460 ✓	700.00
REAR TAILGATE	align	1	2160.00	+	2,160.00
REAR TAILGATE 'LOGO' EMBLEM	new	1	50.00	X	50.00
REAR TAILGATE CENTER REFLECTOR	new	1	496.00	X	496.00
REAR TAILGATE MECHANISM LOCK	new	1	205.00	X	205.00
REAR TAILGATE WEATHER STRIP	} Not new	1	205.00	X	205.00
REAR TAILGATE WINDSCREEN MOULDING		1	260.00	+	260.00
REAR TAILGATE WINDSCREEN MOULDING (SMALL)		1	100.00	+	100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIAW CHIN MIN
83 TOH TUCK PLACE
SINGAPORE 596842

Contact : 97455991 90109991

TAX INVOICE

Repair Code : CLM18487

Date in : 10/12/2024

Vehicle Num. : SJZ5525P

Model : HONDA CIVIC CRX M

Chassis/Eng# : JHMED93700S310032/D16A91605912

	Subtotal before discount	25,640.00
13141 1051280	Percentage discount 20%	5,128.00
	Sub-total 1	20,512.00
FRONT BUMPER CLIPS - SET <i>new</i>	1 80.00	30 80.00
FRONT BUMPER LOWER SPOILER <i>deband</i>	1 1500.00	1000 1,500.00
FRONT BUMPER NUMBER PLATE <i>Best</i>	1 25.00	25.00
FRONT BUMPER NUMBER PLATE HOLDER <i>new</i>	1 50.00	x 50.00
FRONT FENDER INNER SHIELD CLIPS L/R - SET <i>new</i>	2 50.00	x 100.00
RADIATOR (ALUMINIUM) (SARD) <i>Dented</i>	1 2500.00	1900 2,500.00
REAR BUMPER CLIPS - SET <i>new</i>	1 80.00	30 80.00
REAR RH 195/55R15 TYRE <i>cut</i>	1 500.00	180 500.00
REAR RH FENDER GLASS SEALANT <i>new</i>	1 80.00	40 80.00
REAR RH FENDER INNER SHIELD CLIPS - SET <i>new new</i>	1 50.00	x 50.00
REAR RH SHOCK ABSORBER <i>Best</i>	1 2500.00	780 2,500.00
REAR RH SPORT RIM <i>cut</i>	1 1000.00	580 1,000.00
REAR RH TAILLAMP CLIPS - SET <i>new new</i>	1 25.00	x 25.00
REAR TAILGATE WINDSCREEN MOULDING SEALANT <i>3 xop</i>	1 80.00	x 80.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1 80.00	x 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIAW CHIN MIN
83 TOH TUCK PLACE
SINGAPORE 596842

Contact : 97455991 90109991

TAX INVOICE

Repair Code : CLM18487
Date in : 10/12/2024
Vehicle Num. : SJZ5525P
Model : HONDA CIVIC CRX M
Chassis/Eng# : JHMED93700S310032/D16A91605912

Subtotal before discount	8,650.00
Percentage discount 0%	0.00
Sub-total 2	8,650.00
Parts-total	29,162.00

2945

LABOUR

- To remove, change air con parts, vacuums, refill air con gas.
- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall fender glass
- To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.
- To road test driving, check and resetting wheel alignments system.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpets. (to FR)
- To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.
- To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.
- To provide labour, workmanship to change the above damaged body parts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

60 180.00
30 80.00
30 80.00
x 200.00
60 150.00
200 350.00
80 100.00
60 100.00
700 1,200.00
1000 1,400.00
2000 2,800.00
120 200.00
x 80.00

4440

Labour Total 6,920.00
Parts & Labour Total 36,082.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is a computer-generated document which requires no signature. ***

page 5

Adrian Lij
2/s 18/12/24.
12 Days

13 Days

14.3K

total: 1789780
2/s: 14.3K