

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP INC
Xiao Chen

RAJSIA TRANSPORT
113 WOODLANDS STREET 13 #05-102
SINGAPORE 730113

TAX INVOICE

Repair Code : CLM18470

Date in : 25/11/2024

Vehicle Num. : SMM7564X

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR800374844/2ZR0D28325

Contact : 97699389

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR RH FENDER <i>Repair</i>	1	2072.50	2,072.50 +
REAR RH TAILLAMP <i>CR</i>	1	1022.70	1,022.70 +
REAR RH TAILLAMP LOWER GARNISH <i>Repair</i>	1	496.00	496.00 +
Subtotal before discount			3,591.20
Percentage discount 25%			897.80
Sub-total 1			2,693.40
REAR RH DOOR 'AUTO DOOR' STICKER <i>3 pcs</i>	1	150.00	150.00 +
REAR RH DOOR 'PRESS TO OPEN' STICKER	1	120.00	120.00 +
Subtotal before discount			270.00
Percentage discount 0%			0.00
Sub-total 2			270.00
Parts-total			2,963.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Acknowledged by Repairer

Signature:

Date:

Labour Total

Parts & Labour Total

630
80.00 30
80.00 +
1,000.00 500
1,000.00 100
120.00 +
2,280.00
5,243.40

Adrian L
1/5 18/12/24
03 Dec
Total: 1241.25
1/5: 1K (1K)