



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNL 5868B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RH DOOR	BENT	1,864.60	1,675.30
1	FRONT RH DOOR OUTER MOULDING	SERVICEABLE	91.40	-
1	FRONT RH DOOR PILLAR FRAME STICKER	NECESSARY	85.30	85.30
1	FRONT RH DOOR LOWER PROTECTOR	DENTED	238.40	238.40
1	FRONT RH DOOR INNER LOCK	TO REPAIR SEE LABOUR	870.90	-
1	REAR RH SLIDING DOOR	BENT	1,909.10	1,909.10
1	REAR RH SLIDING DOOR OUTER MOULDING	SERVICEABLE	91.50	-
1	REAR RH SLIDING DOOR PILLAR FRAME STICKER	NECESSARY	75.30	75.30
1	REAR RH SLIDING DOOR PILLAR FRAME GARNISH	DENTED	245.30	245.30
1	REAR RH SLIDING DOOR OUTER HANDLE	MTG DENTED	210.50	210.50
1	REAR RH SLIDING DOOR LOWER PROTECTOR	DENTED / DISTORTED	249.10	198.50
1	REAR RH SLIDING DOOR VERTICAL RUBBER	DENTED / CUT	1,184.60	1,184.60
1	REAR RH SLIDING DOOR INNER TRIMBOARD	MTG CRACKED	2,150.30	939.70
1	REAR RH SLIDING DOOR POWER WINDOW MOTOR	DISTORTED	756.70	597.60
1	REAR RH SLIDING DOOR POWER WINDOW GEAR	JAMMED	344.60	344.60
1	REAR RH SLIDING DOOR INNER LOCK	DENTED	1,359.80	1,092.80
1	REAR RH BODY RUBBER	DENTED / CUT	380.40	380.40
1	RH ROCKER PANEL	TO REPAIR SEE LABOUR	466.90	-
1	REAR RH FENDER	TO REPAIR SEE LABOUR	811.40	-
1	REAR RH FENDER GLASS	NOT NECESSARY	524.10	-
	LESS 25% DISCOUNT		-3,477.55	-2,294.35
			10,432.65	6,883.05
<u>SPECIAL NETT ITEMS</u>				
1	FENDER GLASS GUM (SN)	NOT NECESSARY	80.00	-
			80.00	-
<u>LABOUR</u>				
	TO REMOVE AND REPLACE REAR FENDER GLASS.	NOT NECESSARY	120.00	-

Report Ref No. CS/FCI24070024/Kvh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX ROOFLINING AND SEAT CUSHION.		380.00	80.00
	TO REPAIR DAMAGES. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR INNER LOCK, RH ROCKER PANEL AND REAR RH FENDER.		980.00	700.00
	TO SPRAY PAINTING.		1,200.00	800.00
			2,680.00	1,580.00
GRAND TOTAL			13,192.65	8,463.05
RECOMMENDED COST OF REPAIRS				8,463.05

Report Ref No. CS/FCI24070024/Kvh3e2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.