



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: BETTY WONG		Ref: CS/FCI24070024/Kvh3e2(N) Date: 04/03/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7710C	Veh. Inspected	SNL 5868B
Policy No.	D-24101860MFCT	Coverage (\$)	0.00
Claim No.	D24005743MFCT	Excess (\$)	0.00
Assign From	BETTY WONG	Assign Date	01/07/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA (A)	c.c	1490
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	MXPL101022039	Colour	BLUE
Odometer	50462 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	3 mm
L/H Front Tyre	185/65 R15	DUNLOP	3 mm
R/H Rear Tyre	185/65 R15	GITI	9 mm
L/H Rear Tyre	185/65 R15	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/06/2024	Inspection Date	26/07/2024
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #08-09, SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	