



**DICKSON GROUP**  
Your Trusted Automotive Solutionist

**DICKSON AUTO CARE CENTRE PTE LTD**  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

## QUOTATION

### QUOTATION FOR

**NAME:** MS First Capital Insurance Ltd  
**COMPANY NAME:** MS First Capital Insurance Ltd  
**STREET ADDRESS:** 6 Raffles Quay, #21-00  
**POSTAL CODE:** Singapore 048580  
**PHONE:** 6222 2311

**DATE:** 17/12/2024

**REF:** SD0B24CG0005  
**VEHICLE NO:** SLM2680M  
**MAKE:** NISSAN  
**MODEL:** QASHQAI  
**PREPARED BY:** XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>LABOUR</u>						
1	TO REMOVE & REPLACE BUMPER REAR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$250.00	\$ 250.00		\$ 250.00
2	TO SPRAY BUMPER REAR	1		\$250.00	\$ 250.00		\$ 250.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$100.00	\$ 100.00		\$ 100.00
4	TO TRANSFER ALL BUMPER REAR SENSOR	1		\$200.00	\$ 200.00		\$ 200.00
	<u>PARTS</u>						
1	BUMPER REAR	1		\$946.50	\$ 946.50		\$ 946.50
2	BUMPER CLIPS	10		\$5.00	\$ 50.00		\$ 50.00
3	SENSOR REAR [SET]	1		\$250.00	\$ 250.00		\$ 250.00
4	TOW EYE COVER REAR RH	1		\$43.10	\$ 43.10		\$ 43.10
SUBTOTAL					\$ 2,089.60	SUBTOTAL	\$ 2,089.60
GST 9%					\$ 188.06	GST 9%	\$ 188.06
TOTAL					\$ 2,277.66	TOTAL	\$ 2,277.66

### REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(CUSTOMER'S SIGNATURE AND  
COMPANY STAMP)

(AUTHORISED SIGNATURE)