

Veron

ESTIMATE OF REPAIR

Veh# : SKN4200J

Model: TOYOTA ESTIMA

Accident Date : 14/12/2024

11/6/2014 - 31/5/2034

Location : WOODLANDS INDUSTRIAL PARK D STREET 1

3P: FBT5194L (NTUC)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tailgate <i>Dented</i> <i>2401</i>	2,669.60	✓	
2	1 pc	Rear tailgate outer chrome moulding <i>new</i>	294.00	+	
3	1 pc	Rear tailgate Logo <i>new</i>	74.30	✓	
4	1 pc	Rear tailgate emblem - ESTIMA <i>3 pc</i>	68.80	✓	
5	1 pc	Rear tailgate emblem - AERAS	80.40	✓	
6	1 pc	Rear tailgate lock <i>Damaged</i>	576.80	✓	
7	1 pc	Rear tailgate weatherstrip <i>new cut</i> <i>39</i>	518.50	✓	
8	1 pc	Rear tailgate inner trim garnish <i>new torn</i>	680.70	✓	
9	1 set	Rear tailgate inner trim garnish clip <i>new</i>		50.00	+
10	1 pc	Rear tailgate windscreen glass moulding <i>new</i>	141.20	✓	
11	1 pc	Rear tailgate windscreen glass sealant <i>new</i>		80.00	60
12	1 pc	Rear bumper <i>Dented</i>	954.80	✓	
13	2 pcs	Rear bumper side retainer R/L <i>new</i>	179.20	+	
14	2 pcs	Rear bumper side bracket R/L <i>new</i>	124.80	+	
15	1 set	Rear bumper clip <i>new</i>		50.00	30
16	1 pc	Rear end panel <i>Dented</i> <i>890</i>	1,159.80	✓	
17	1 pc	Rear end panel sealant <i>new</i>		80.00	60
18	1 pc	Rear end panel top cover garnish <i>2 pc</i>	391.90	✓	
19	1 pc	Rear end panel lower cover garnish <i>1 pc</i>	299.10	✓	
20	1 set	Rear end panel cover garnish clip <i>new</i>		50.00	20
21	1 pc	Rear end lower panel <i>Dented</i> <i>750</i>	1,214.70	✓	
22	1 pc	Rear trim carpet garnish <i>new</i>	550.80	+	
23	1 set	Rear trim carpet garnish clip <i>new</i>		50.00	+
24	1 pc	Rear no. plate <i>new</i>		35.00	+
25	1 pc	Rear no. plate holder <i>new</i>		50.00	+
		Sub Total:	9,980.40	445.00	0.00
			25%	0%	10%
		After Less %:	7,485.30	445.00	0.00

7704 SN: 170
5778

	Labour	
1	To remove & refix accident damaged parts & realign accident affected area.	1,400.00 800 900
2	To spray paint on accident affected area.	1,000.00 800
3	To remove & refix rear tailgate windscreen glass.	150.00 120
4	To remove & refix rear tailgate mechanism & check for function.	80.00 80
5	To remove & refix rear side covering, trim garnish & other attachment parts.	150.00 80
6	To rust proof affected area.	80.00 80
	Sub Total:	2,860.00
	Total:	10,790.30

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



AL 8778 1999
24 hr accident call



06 Day

total: 8008

L/s: 6.4K

6.4k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: