



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: JASON TEA		Ref: CS/FCI24120274/Aqp3m4(N) Date: 05/05/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4387C	Veh. Inspected	SMW 5667T
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010999MFCT	Excess (\$)	0.00
Assign From	SWEE KEONG TEO	Assign Date	18/12/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY HYBRID	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTNB23HK003064530	Colour	WHITE
Odometer	139445 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R17	TRANSFORCE	6 mm
L/H Front Tyre	215/60R17	TRANSFORCE	6 mm
R/H Rear Tyre	215/60R17	TRANSFORCE	6 mm
L/H Rear Tyre	215/60R17	TRANSFORCE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/12/2024	Inspection Date	18/12/2024
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	