

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

JinAuto

Tel: 62898126 Fax: 62870590

Email: jin@jinauto.com.sg

Company Reg No: 200704370C , GST Reg No : 200704370C

M/S COMFORT DELGRO

16-12-24

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA HARRIER - SLE9804U

DOA : 14/12/2024

S/N	QTY	DESCRIPTION	AMOUNT
1	1 PC	TAILGATE	\$ 2175.40 <i>bt</i>
2	1 PC	TAILGATE LOCK	\$ 647.10 <i>X nn</i>
3	1 PC	TAILGATE EMBLEM	\$ 79.60 <i>ucl</i>
4	1 PC	TAILGATE "HARRIER" EMBLEM	\$ 84.90 <i>ucl</i>
5	1 PC	TAILGATE WEATHERSTRIP RUBBER	\$ 515.40 <i>X nn</i>
6	1 PC	REAR BUMPER	\$ 2336.30 <i>de</i>
7	1 PC	REAR BUMPER LOWER	\$ 649.40 <i>de</i>
8	1 PC	REAR BUMPER LOWER RED REFLECTOR - LH	\$ 91.80 <i>cnr</i>
9	1 PC	REAR BUMPER SIDE RETAINER - LH	\$ 156.40 <i>X nn</i>
10	1 PC	REAR BUMPER SIDE RETAINER - RH	\$ 156.40 <i>X</i>
11	1 PC	END PANEL	\$ 1252.20 <i>X bt</i>
12	1 PC	END PANEL TOP GARNISH	\$ 501.20 <i>X nn</i>
13	1 PC	REAR TAIL LAMP - LH	\$ 736.40 <i>X nn</i>
14	1 PC	SPARE TYRE PANEL	\$ 1392.85 <i>X nn</i>
			\$ 9382.50
		Less 25%	\$ -2345.62
			\$ 7036.88
15	1 SET	REVERSE SENSOR	\$ 280.00 <i>200mm</i>
16		SEALANT & GUM	\$ 100.00 <i>60</i>
17	1 SET	BUMPER CLIPS	\$ 70.00 <i>40</i>
18		SPRAY PAINTING	\$ 950.00 <i>750</i>
19		LABOUR CHARGE	\$ 1100.00 <i>800</i>
20		WIRING	\$ 50.00 <i>30</i>
21		LABOUR FOR REVERSE SENSOR	\$ 80.00 <i>30</i>
22		TUFF KOTE	\$ 80.00 <i>30</i>
23		LABOUR FOR REAR WINDSCREEN	\$ 120.00 <i>✓</i>
24		REMOVE AND REFIX CARPET ,GARNISHES	\$ 80.00 <i>60</i>
			\$ 9946.88

Tanjiu 97495749 / 62563561
'wp' 18/12/24 @ 430 PM

tanjiu@khanh.com
c/s Resurvey after repair
6 days

8062.45
6046.84
300
1820
6046.84
300
1820
8166.84
LS\$6500
6 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Co.

Acknowledged by Repairer

Signature:

Date: