

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 23 Dec 2024

Preliminary Advice

Vehicle No	: YN6032Z	Accident Date	: 29/11/2024
Make	: MITSUBISHI CANTER	Policy No.	: MCV24A00007700
Assignment Date	: 18/12/2024	Excess	: S\$1,600.00
Date of Inspection	: 20/12/2024	Est. Duration of Repair	: 10
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29 SINGAPORE 533758		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,870.25
Revised Amount	:S\$	9,454.50
Check Items (Estimated)	:S\$	22,574.50
Total	:S\$	32,029.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	32,175.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,825.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.
Pending repair cost from repairer.