

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | | |
|--|--|---|----------------|--------------------------|-------------------------|--|
| | INCOME INSURAN | | Ref: | CS/INC24120282/Avh3e2(N) | | |
| | 75 BRAS BASAH R INCOME CENTRES | | Date: | 06/05/2025 | | |
| | ATTN: MARCUS X | IAO | | Code: | INC | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SMQ 2125S | Veh. Inspected | d | SNB 9094T | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/1308917-001 | Excess (\$) | | 0.00 | |
| | Assign From | MARCUS XIAO | Assign Date | | 18/12/2024 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA CIVIC | c.c | | 1597 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2021 | |
| | Chassis No. | MRHFC5650LT000710 | Colour | | GREY | |
| | Odometer | 60447 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/55 R16 | MICHELIN | | 6 mm | |
| | L/H Front Tyre | 215/55 R16 | MICHELIN | | 6 mm | |
| | R/H Rear Tyre | 215/55 R16 | MICHELIN | | 6 mm | |
| | L/H Rear Tyre | 215/55 R16 | MICHELIN | | 6 mm | |
| 4. | 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| | | | | | T ₂ | |
| 5. | General Information | | | | | |
| | Accident Date | 15/12/2024 | Inspect Date / | Time | 19/12/2024 (01:17 PM) | |
| | Survey held at | AKA AUTO PTE LTD | | | | |
| | 25 KAKI BUKIT ROAD 4, #05-36, SYNERGY @ KB, SINGAPORE 417800 | | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |
| | • | | | | | |