



AKA AUTO PTE LTD
25 KAKI BUKIT ROAD 4,
#05-36, #05-37
SYNERGY @ KB
S417800
H: 81880754
ROC: 201700008R

TP INC.
Veron

19-Dec-24

ESTIMATED REPAIR CHECKLIST

TO : NTUC INCOME
ATTENTION : MOTOR INSURANCE CLAIM
CLAIM TYPE : 3RD PARTY CLAIM
ACCIDENT DATE/TIME :

VEHICLE REGISTRATION NO.: SNB9094T (2021)
VEHICLE MAKE/MODEL: HONDA / CIVIC
CHASSIS NUMBER: MRHFC5650LT000710
CONTACT PERSON :

PARTS	QTY	PER UNIT	PRICES
1 REAR BUMPER <i>Repair</i>	1	\$ 617.20	\$ + 617.20
2 REAR BUMPER SIDE HOLDER	1	\$ 39.40	\$ + 39.40
3 REAR KNUCKLE ARM	1	\$ 410.50	\$ + 410.50
4 REAR LOWER ARM	1	\$ 350.90	\$ + 350.90
5 REAR WHEEL HUB C/W BEARING	1	\$ 294.40	\$ + 294.40
6 REAR SHOCK ABSORBER	1	\$ 310.20	\$ + 310.20
7 REAR FENDER <i>Repair</i>	1	\$ 1,359.90	\$ + 1,359.90
8 REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 129.80	\$ + 129.80
9 REAR DOOR <i>Dented</i>	1	\$ 922.50	\$ + 922.50
10 REAR DOOR LOCK	1	\$ 191.30	\$ + 191.30
11 REAR DOOR WEATHERSTRIPE <i>new</i>	1	\$ 107.20	\$ + 107.20
12 REAR DOOR INNER TRIM BOARD <i>new</i>	1	\$ 465.80	\$ + 465.80
13 ROCKER PANEL OUTER GARNISH <i>Dented</i>	1	\$ 560.40	\$ + 560.40
14 FRONT DOOR	1	\$ 949.70	\$ + 949.70
15 FRONT DOOR LOCK <i>new</i>	1	\$ 181.20	\$ + 181.20
16 FRONT DOOR WEATHERSTRIPE <i>new</i>	1	\$ 78.50	\$ + 78.50
17 FRONT DOOR INNER TRIM BOARD <i>new</i>	1	\$ 455.70	\$ + 455.70
18 FRONT DOOR GLASS REGULATOR GEAR C/W MOTOR <i>new</i>	1	\$ 359.40	\$ + 360.10
19 FRONT DOOR WING MIRROR <i>Dented</i>	1	\$ 685.40	\$ + 685.40
20 FRONT DOOR WING MIRROR OUTER COVER <i>Missing</i>	1	\$ 69.90	\$ + 69.90
21 FRONT FENDER <i>Repair</i>	1	\$ 450.80	\$ + 450.80
		Sub total	SUBTOTAL : \$ 8,990.80
		Less 20%	LESS 20% : \$ 1,798.16
		Total List	PARTS TOTAL : \$ 7,192.64

3187.90
2550.32

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ + 30.00
2 REAR TYRE <i>new</i>	1	\$ 300.00	\$ + 300.00
3 REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 60.00	\$ + 60.00
4 REAR FENDER SEALANT <i>new</i>	1	\$ 60.00	\$ + 60.00
5 REAR DOOR INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ + 30.00
6 REAR DOOR BLACK TAPE <i>new</i>	1	\$ 60.00	\$ + 60.00
7 ROCKER PANEL OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 50.00	\$ + 50.00
8 FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ + 30.00
9 FRONT DOOR BLACK TAPE <i>new</i>	1	\$ 60.00	\$ + 60.00
		Sub total	S/N TOTAL : \$ 680.00

120

LABOUR CHARGES		PRICES	ADJUSTMENT
1	PANEL BEATING	\$ 1,600.00	600
2	SPRAY PAINTING	\$ 1,600.00	1300
3	WIRING	\$ 50.00	30
4	TO APPLY TUFF COAT	\$ 150.00	50
5	TO REMOVE REVERSE SENSOR	\$ 100.00	X
6	TO REMOVE REAR WINDSCREEN	\$ 180.00	X
7	TO REMOVE UPHOLSTERY	\$ 150.00	X
8	TO REMOVE REAR UNDERCARRIAGE	\$ 380.00	X
9	TO TRANSFER FRONT & REAR DOOR FITTINGS	\$ 300.00	120
10	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	X
LABOR TOTAL :		\$ 4,660.00	

2100.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2770.32

L/S: 3.8K

05 Days.

3.8K.