



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE MANGUBAT

Ref: CS/INC24120284/Anh3e2(N)

Date: 10/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 4651G	Veh. Inspected	SLL 371Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1308713-002	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	19/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NSP1707032147	Colour	BROWN
Odometer	104332 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	6 mm
L/H Front Tyre	185/65 R15	DUNLOP	6 mm
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/12/2024	Inspect Date / Time	19/12/2024 (01:04 PM)
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**