



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070026/Dqp3m4
16 RAFFLES QUAY	Date:	05/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9018R	Veh. Inspected	SHC 2115D
Policy No.	-	Coverage	0
Claim No.	D24005704MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	01/07/2024

2. Vehicle Details

Make & Model	HYUNDAI IONIQ	C.C	1580
Engine No.	G4LEJU080651	Year of Reg.	03/09/2018
Chassis No.	KMHC851CVKU107420	Colour	BLUE
Odometer	634944 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WEST LAKE	5
L/H Front Tyre	195/65R15	WEST LAKE	5
R/H Rear Tyre	195/65R15	WEST LAKE	5
L/H Rear Tyre	195/65R15	WEST LAKE	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/06/2024	Inspection Date	02/07/2024
Survey held at	BIFROST AUTO PTE LTD - 59 LOYANG DRIVE LEVEL 4 ROOM 7 (S) 508969		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days