

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

WITHOUT PREJUDICE

VEHICLE NO : GBM3682U

MAKE & MODEL : SHINERAY / X30LEV V2.0

CHASSIS NO : LM6CKD2XXPX002346

TO : MS First Capital Insurance Ltd

DATE : 18/12/2024

CLAIM TYPE : TP CLAIM

D.O.A : 16/12/2024

REPAIR QUOTATION

Parts

S/No.	QTY	DESCRIPTION	CONDITION	LIST PRICE	TOTAL LIST PRICE
1	1	FRONT DOOR RH	DD	\$ 1,425.10	\$ 1,425.10
2	1	FRONT DOOR RH HINGE UPPER	X SVC	\$ 167.00	\$ 167.00
3	1	FRONT DOOR RH HINGE LOWER	X SVC	\$ 167.00	\$ 167.00
4	1	SIDE MIRROR RH	X SVC	\$ 275.00	\$ 275.00
5	1	FRONT FENDER RH	DD	\$ 475.00	\$ 475.00
6	1	FRONT FENDER EMBLEM RH	NGL	\$ 75.00	\$ 75.00
7	1	FRONT BUMPER	X R	\$ 575.00	\$ 575.00
8	1	FOG LAMP COVER RH	CRA	\$ 100.00	\$ 100.00
9	1	HEADLAMP RH	X SVC	\$ 380.00	\$ 380.00
10	1	EV CHARGING POT COVER	DD	\$ 240.00	\$ 240.00
11	1	FRONT TYRE SENSOR RH	X SVC	\$ 510.00	\$ 510.00
12	1	TIE ROD END RH	RT	\$ 292.60	\$ 292.60
13			SUPPLEMENTARY		
TOTAL PARTS				\$ 2,607.70	\$ 4,681.70

SUB TOTAL PRICE

\$ 2,607.70

LESS 10%

\$ 260.77

TOTAL PRICE

\$ 2,346.93

SUB TOTAL PRICE

\$ 4,681.70

LESS 10%

\$ 468.17

TOTAL PRICE

\$ 4,213.53

Special Nett

S/No.	QTY	DESCRIPTION	CONDITION	ADJUSTERS PRICING	TOTAL S/NETT
1	1	FRONT DOOR RH COMPANY STICKER	NEL	\$ 35.00	\$ 35.00
2	1	RIM FRONT RH	DD	\$ 450.00	\$ 450.00
3	1	TYRE FRONT RH	X SVC	\$ -	\$ 150.00
4					
TOTAL S/NETT				\$ 385 485.00	\$ 635.00

Labour Charges

DESCRIPTION	REMARKS	ADJUSTERS PRICING	WORKSHOP PRICING
1	TO DISMANTLE & REFIT BODY PARTS TO REPAIR & RE-ALIGN ACCIDENT PPORTION	\$ 700.00	\$ 1,200.00
2	TO REMOVE & REFIT FRONT DOOR RH WINDOW CHANNEL AND LOCK	\$ 120.00	\$ 300.00
3	TO PUTTY & RE-SPRAY FRONT RH DOOR , LOWER DOOR PANEL , FRONT BUMPER , FRONT FENDER AND MINOR TOUCH UP	\$ 700.00	\$ 1,200.00
4	TO CHECK HEADLAMP WIRING & RESET FAULT CODE	\$ -	\$ 150.00
5	TO APPLY ANTI-RUST COROSSIN	\$ 50.00	\$ 100.00
6	TO DO WHEEL ALIGNMENT & BALANCING	\$ -	\$ 200.00
7	CAR WASH & GROOMING	\$ 20.00	\$ 20.00
8			
TOTAL LABOUR		\$ 1,590.00	\$ 3,170.00

Total Cost of Repairs

\$ 4,421.93

\$ 8,018.53

(Total Parts + Total S/Nett + Total Labour Cost)

PARTS \$2,182.60
LESS 10% \$1,964.34
385.00

SIN
LABOUR \$1,590.00
\$3,939.34 / 4 REPAIR DAYS

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

WITHOUT PREJUDICE

VEHICLE NO : GBM3682U
MAKE & MODEL : SHINERAY / X30LEV V2.0
CHASSIS NO : LM6CKD2XXPX002346
TO : MS First Capital Insurance Ltd

DATE : 18/12/2024
CLAIM TYPE : TP CLAIM
D.O.A : 16/12/2024

SUPPLEMENTARY

Parts

S/No.	QTY	DESCRIPTION	CONDITION	LIST PRICE	TOTAL LIST PRICE
1	1	TIE ROD END RH	RT	\$ 292.60	\$ 292.60
2					
TOTAL PARTS					\$ 292.60

SUB TOTAL PRICE	\$ 292.60
LESS 10%	\$ 29.26
TOTAL PRICE	\$ 263.34

Special Nett

S/No.	QTY	DESCRIPTION	CONDITION	UNIT S/NETT	TOTAL S/NETT
1	0	N/A	N/A	\$ -	\$ -
TOTAL S/NETT					\$ -

Labour Charges

		DESCRIPTION	REMARKS	ADJUSTERS PRICING	WORKSHOP PRICING
1		N/A	N/A	\$ -	\$ -
TOTAL LABOUR					\$ -

Total Cost of Repairs \$ 263.34
(Total Parts + Total S/Nett + Total Labour Cost)

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

WITHOUT PREJUDICE

VEHICLE NO : GBM3682U
MAKE & MODEL : SHINERAY / X30LEV V2.0
CHASSIS NO : LM6CKD2XXPX002346
TO : MS First Capital Insurance Ltd

DATE : 18/12/2024
CLAIM TYPE : TP CLAIM
D.O.A : 16/12/2024

REPAIR QUOTATION

Parts

S/No.	QTY	DESCRIPTION	CONDITION	LIST PRICE	TOTAL LIST PRICE
1	1	FRONT DOOR RH	/ DD	\$ 1,425.10	\$ 1,425.10
2	1	FRONT DOOR RH HINGE UPPER	X SVC	\$ 167.00	\$ 167.00
3	1	FRONT DOOR RH HINGE LOWER	X SVC	\$ 167.00	\$ 167.00
4	1	SIDE MIRROR RH	X SVC	\$ 275.00	\$ 275.00
5	1	FRONT FENDER RH	/ DD	\$ 475.00	\$ 475.00
6	1	FRONT FENDER EMBLEM RH	/ NEC	\$ 75.00	\$ 75.00
7	1	FRONT BUMPER	X R	\$ 575.00	\$ 575.00
8	1	FOG LAMP COVER RH	/ CRA	\$ 100.00	\$ 100.00
9	1	HEADLAMP RH	X SVC	\$ 380.00	\$ 380.00
10	1	EV CHARGING POT COVER	/ DD	\$ 240.00	\$ 240.00
11	1	FRONT TYRE SENSOR RH	? X SVC	\$ 510.00	\$ 510.00
12					
TOTAL PARTS					\$ 4,389.10

SUB TOTAL PRICE \$ 4,389.10
LESS 10% \$ 438.91
TOTAL PRICE \$ 3,950.19

Special Nett

S/No.	QTY	DESCRIPTION	CONDITION	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT DOOR RH COMPANY STICKER	/ NEC	\$ 35.00	\$ 35.00
2	1	RIM FRONT RH	/ DD	\$ 450.00	\$ 450.00
3	1	TYRE FRONT RH	X SVC	\$ 150.00	\$ 150.00
4					
TOTAL S/NETT					\$ 635.00

Labour Charges

DESCRIPTION	REMARKS	ADJUSTERS PRICING	WORKSHOP PRICING
1 TO DISMANTLE & REFIT BODY PARTS TO REPAIR & RE-ALIGN ACCIDENT PPORTION		700	\$ 800 1,200.00
2 TO REMOVE & REFIT FRONT DOOR RH WINDOW CHANNEL AND LOCK			\$ 120 300.00
3 TO PUTTY & RE-SPRAY FRONT RH DOOR, LOWER DOOR PANEL, FRONT BUMPER, FRONT FENDER AND MINOR TOUCH UP		700	\$ 1,200.00
4 TO CHECK HEADLAMP WIRING & RESET FAULT CODE		NN X	\$? 150.00
5 TO APPLY ANTI-RUST COROSSIN		50	\$ 100.00
6 TO DO WHEEL ALIGNMENT & BALANCING	X NN	show nra 3	\$ 200.00
7 CAR WASH & GROOMING			\$ - NEC 20.00
8			
TOTAL LABOUR			\$ 3,170.00

Total Cost of Repairs

\$ 7,755.19

(Total Parts + Total S/Nett + Total Labour Cost)

NAZ LKIC
19/12/2024 1635
PIP
CHECK ITEM PHOTOS
BEFORE PAINT PHOTOS
4 DAYS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: