



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBM 3682U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR RH	DENTED	1,425.10	1,000.00
1	FRONT DOOR RH HINGE UPPER	SERVICEABLE	167.00	-
1	FRONT DOOR RH HINGE LOWER	SERVICEABLE	167.00	-
1	SIDE MIRROR RH	SERVICEABLE	275.00	-
1	FRONT FENDER RH	DENTED	475.00	475.00
1	FRONT FENDER EMBLEM RH	NECESSARY	75.00	75.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	575.00	-
1	FOG LAMP COVER RH	CRACKED	100.00	100.00
1	HEADLAMP RH	SERVICEABLE	380.00	-
1	EV CHARGING POT COVER	DENTED	240.00	240.00
1	FRONT TYRE SENSOR RH	SERVICEABLE	510.00	-
1	TIE ROD END RH (ADDITIONAL)	BENT	292.60	292.60
	LESS 10% DISCOUNT		-468.17	-218.26
			4,213.53	1,964.34
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR RH COMPANY STICKER (SN)	NECESSARY	35.00	35.00
1	RIM FRONT RH (SN)	DENTED	450.00	350.00
1	TYRE FRONT RH (SN)	SERVICEABLE	150.00	-
			635.00	385.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE & REFIT BODY PARTS TO REPAIR & RE-ALIGN ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	700.00
	TO REMOVE & REFIT FRONT DOOR RH WINDOW CHANNEL AND LOCK.		300.00	120.00
	TO PUTTY & RE-SPRAY FRONT RH DOOR, LOWER DOOR PANEL, FRONT BUMPER, FRONT FENDER AND MINOR TOUCH UP.		1,200.00	700.00
	TO CHECK HEAD LAMP WIRING & RESET FAULT CODE.	NOT NECESSARY	150.00	-
	TO APPLY ANTI-RUST COROSSIN.		100.00	50.00
	TO DO WHEEL ALIGNMENT & BALANCING.	NOT NECESSARY	200.00	-

Report Ref No. CS/FCI24120289/Nnp3e2(N)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CAR WASH & GROOMING.		20.00	20.00
			3,170.00	1,590.00
GRAND TOTAL			8,018.53	3,939.34
RECOMMENDED COST OF REPAIRS				3,939.34

Report Ref No. CS/FCI24120289/Nnp3e2(N)

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.