



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: EILEEN WANG			Ref: CS/FCI24120289/Nnp3e2(N) Date: 24/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6926Z	Veh. Inspected	GBM 3682U	
Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
Claim No.	D24011016MFCT	Excess (\$)	0.00	
Assign From	EILEEN WANG CHAI LING	Assign Date	18/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	SHINERAY X30LEV V2.0	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2023	
Chassis No.	LM6CKD2XXPX002346	Colour	WHITE	
Odometer	10544 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	FARROAD	5 mm	
L/H Front Tyre	175/70 R14	FARROAD	5 mm	
R/H Rear Tyre	175/70 R14	FARROAD	6 mm	
L/H Rear Tyre	175/70 R14	FARROAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/12/2024	Inspection Date	19/12/2024	
Survey held at	EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD 37 LOYANG WAY, LOYANG INDUSTRIAL ESTATE, SINGAPORE 508734			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		