



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24120290/Kvh3m4(N)

Date: 08/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 1986K	Veh. Inspected	SLU 9930D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1306793-002	Excess (\$)	0.00
Assign From	ANNA YEO	Assign Date	19/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZSU600091476	Colour	METALLIC PEARL WHITE
Odometer	106662 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55R18	VIKING	6 mm
L/H Front Tyre	235/55R18	VIKING	6 mm
R/H Rear Tyre	235/55R18	VIKING	8 mm
L/H Rear Tyre	235/55R18	VIKING	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/12/2024	Inspect Date / Time	03/01/2025 (04:17 PM)
Survey held at	5034 ANG MO KIO IND PARK 2 #01-341 S569537		
Repairer	JD MOTORSPORTS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days