

ASS. REC. BY:

REF: VNC/ CS/INC24120290/Kvh3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s TDof 9831Insured: SLW 1986K

Policy No. _____

Claims No. MT/1306793-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 64k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

6/11/24 8:27:50L Car (red 12,631.87, 82%)

Veh No: SLW 99300 Yr Regn: 12, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Harter C.C. 1988Colour M. P. White A/C: Insured / Std / NH / NASp. Reading 106682 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2 PU 60 0091476Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 235/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 1/12/24

Survey held at _____

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 3/1/2025

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL



MOTORSPORTS



JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 02-01-2025
VEHICLE : SLU9930D
MAKE/MODEL : TOYOTA / HARRIER
CHASSIS NO : ZSU60-0091476
MILLAGE : 105400 KM
DOA : 01-12-24
TP INSURANCE : INCOME INSURANCE LIMITED

Not Authoite
1/1 Rm & 2750h
Permy After Rain
4 days

List items

01 PC	REAR BUMPER	1381.80	By \$	2,265.42	✓
01 PC	REAR RH BUMPER SIDE RETAINER		Ln \$	93.04	X
01 PC	REAR BUMPER DISFFUSER		\$ Ln	543.18	X
01 PC	REAR BUMPER INNER SPONGE		\$ Ln	299.10	X
01 PC	REAR RH FENDER		\$ Ln	2,048.91	X
01 PC	REAR RH FENDER INNER SHEILD		\$ Ln	369.50	X
01 PC	REAR RH DOOR	1606.00	warp/By \$	2,155.50	✓
01 PC	REAR RH FENDER OUTER CHROME MOULDING		\$ Ln	232.10	X
01 PC	REAR RH ROCKER PANEL		\$ Ln	678.40	X
01 PC	REAR RH FENDER GANISH		\$ Ln	958.00	X
01 PC	REAR RH MUPFLAT		\$ Ln	93.52	X
01 PC	REAR RH WHEEL BEARING		svr	385.20	X
			\$	10,121.87	

258

Special Nett Item:

01 PC	REAR RH RIM	6.8	Pen \$	800.00	1000
01 PC	REAR RH TYRES		\$ Ln	250.00	X
01 PC	PANEL SEALANT		\$ Ln	60.00	X
			\$	1,110.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR
6. TO SUPPLY LABOUR TO CHANGE UNDER CARRIAGE PARTS
7. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING
8. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT

50d	\$	1,800.00
60d	\$	1,200.00
nn	\$ x	200.00
	\$ 2d	200.00
nn	\$ x	300.00
nn	\$ x	200.00
nn	\$ x	100.00
nn	\$ x	150.00
	\$	<u>4,150.00</u>

TOTAL PARTS

\$ 10,121.8'

SPECIAL NETT ITEM

\$ 1,110.00

TOTAL LABOUR

\$ 4,150.00

TOTAL COST OF REPAIR

\$ 15,381.8'

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: