

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

First

TP 1st Cap.
Veron

Owner : Rusnani Bte Idrus
(0601172659586)

Accident Date : 10-Dec-24

Vehicle No : SD8160V (DOR: 14052023)

Vehicle Model : Yamaha Y16ZR
DOXOU

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy } new	\$ 640.00 +
1	Fork under bracket } new	\$ 225.00 +
1	Handle-bar Best	\$ 285.00 - 135
1	Handle-bar end ut	\$ 136.00 - 45
1	Hand grip (1 set) new	\$ 98.00 +
1	Front Signal new	\$ 280.00 +
1	Pilot Light new	\$ 880.00 +
1	Clutch lever ut	\$ 115.00 - 40
1	Front cover - matt ut	\$ 200.00 -
1	Side mirror ut	\$ 128.00 - 60
1	Fairing assy (1 set) could	\$ 780.00 - 450
1	Front footrest bracket new	\$ 255.00 +
2	Front footrest ut	\$ 168.00 - 80
1	Gear pedal ut	\$ 125.00 -
2	Rear footrest ut	\$ 145.00 - 65
1	Rear footrest bracket ut	\$ 250.00 - 125
1	Swing arm new	\$ 685.00 +
1	Swing arm shaft new	\$ 180.00 +
1	Rear rim shaft new	\$ 165.00 +
1	Rear rim new	\$ 650.00 +
1	Rear brake disc new	\$ 225.00 +
1	Rear lamp could	\$ 455.00 - 250
1	Rear fender Smoked	\$ 225.00 -
1	Rear fender bracket Best	\$ 380.00 - 250
1	Rear signals Lt Smoked	\$ 180.00 - 60
1	Rear number plate lamp smoked	\$ 145.00 - 70
1	Rear cover (matt) could	\$ 168.00 - 120
1	Exhaust assy new	\$ 685.00 +
1	Exhaust protector } ut	\$ 135.00 -
1	Exhaust pipe end cover } ut	\$ 105.00 -
		\$ 9,093.00
	Less 10%	\$ 909.30
		\$ 8,183.70

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Rusnani Bte Idrus
(0601172659586)

Accident Date : 10-Dec-24

Vehicle No : SD8160V (DOR: 14052023)

Vehicle Model : Yamaha Y16ZR
DOXOU

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>Best</i>	\$	38.00 <i>20</i>
2	Fork oils <i>3 new</i>	\$	30.00 <i>+</i>
2	Fork oil seals	\$	56.00 <i>+</i>
1	Steering cone (1 set) <i>new</i>	\$	120.00 <i>+</i>
1	Sticket (1 set) <i>new</i>	\$	100.00 <i>60</i>
		\$	344.00

S/No.	Labour		
1	To provide towing service (LOD) S\$70.00	\$	- <i>?</i>
2	To ckeck wiring and reset headlamp focusing <i>480</i>	\$	80.00 <i>30</i>
3	To provide labour	\$	420.00 <i>250</i>
4	To repair body frame	\$	480.00 <i>200</i>
		\$	980.00
Grand Total		\$	9,507.70

Singapore Dollars: Nine Thousand Five hundred Seven and Cents: Seventy only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
L/S 19/12/24

0422

Total: 2855
L/S: 2250.