

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120293/KVP3E2
Date: 13/01/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003519432
Claimant Vehicle No :	SNG1428R	Insured Vehicle No :	SNQ3752M
Date of Loss:	15/12/2024	Nature of Claim:	TP
		Claim No:	385409

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG1428R		
Make & Model:	TOYOTA COROLLA ALTIS, 1.8 4DR SEDAN (2WD) HYBRID (A)	Engine No:	2ZRY836963
Reg. Date:	12/07/2022 (Man. Year: 2022)	Chassis No:	MR2BZ3BE400009298
Colour:	Metallic Silver	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Celimo 3 mm	Rear Left Side:	TURISMO 4 mm
Front Right Side:	Celimo 3 mm	Rear Right Side:	TURISMO 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,250.90	3,062.00	4,188.90	57.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,460.00	1,200.00	45.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,910.90	4,522.00	5,388.90	54.37
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	9,910.90	3,600.00	6,310.90	63.68
+ GST 9.00/9.00% (S\$)	891.98	324.00	567.98	63.68
Nett Amount (S\$)	10,802.88	3,924.00	6,878.88	63.68

INSPECTION

Date of Assignment:	19/12/2024	
Date Inspected:	19/12/2024	Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (Kranji) 60 Jalan Lam Huat #05-67/68, Carros Centre Singapore 737869
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2025)
Parts:	143	TOYOTA COROLLA ALTIS 1.8 4DR SEDAN (2WD) HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG1428R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	850.00 FL	*798.00 FL
2	2		*REAR BUMPER SENSOR	Serviceable	778.20 FL	*- FL
3	1		*REAR BUMPER RETAINER LH	Serviceable	105.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	397.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR LH	Serviceable	68.00 FL	*- FL
6	1		*TAILLAMP LH	Serviceable	712.00 FL	*- FL
7	1		*REAR FENDER LH	Repair	1,025.00 FL	*- FL
8	1		*REAR FENDER COWLING LH	Serviceable	212.00 FL	*- FL
9	1		*REAR DOOR LH	Dented / Warped	1,258.00 FL	*1,258.00 FL
10	1		*REAR WHEEL BEARING LH	Not Necessary	251.00 FL	*- FL
11	1		*REAR BLINDSPORT SENSOR LH	Serviceable	1,125.00 FL	*- FL
12	1		*REAR SPORT RIM LH	Dented	1,200.00 FS	*1,200.00 FS
13	1		*REAR TYRE LH	Serviceable	250.00 FS	*- FS
14	1		*REAR DOOR STICKER LH	Necessary	500.00 FS	*180.00 FS
15	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*40.00 FS
16	1		*REAR BUMPER STICKER	Necessary	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,946.20	3,576.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,695.30	514.00
Total Parts (S\$)	7,250.90	3,062.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	800.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	800.00
3	REMOVE AND REFIX REAR UNDERCARRIAGE	New	300.00	0.00
4	CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
5	TUFF COAT	New	250.00	30.00
6	WIRING CHECK	New	80.00	20.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
Gross Labour Cost (\$)			2,660.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >