

ASS. REC. BY:

REF: MSG-1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F: Seimo 225/45 R17R: Turismo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S - RS. SI

: Fuel

: Others

Report Format :

p Sum / I.B.I: (\$

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 2016058782)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 93911482

Not Notation
C/Sy &
Meeting After Pains
5 days

TO :	DATE : 19-Dec-24
ATTENTION : MOTOR CLAIMS DEPT	JOB TYPE : T/P CLAIM
VEHICLE DETAILS	
	VEHICLE NO : SNG1428R
	MODEL : TOYOTA ALTIS

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>CM</i>	1	\$ 850.00	\$ 850.00
2	REAR BUMPER SENSOR <i>pu</i>	2	\$ 389.10	\$ 778.20
3	REAR BUMPER RETAINER LH	1	\$ 105.00	\$ 105.00
4	REAR BUMPER REINFORCEMENT	1	\$ 397.00	\$ 397.00
5	REAR BUMPER REFLECTOR LH <i>pu</i>	1	\$ 68.00	\$ 68.00
6	TAILAMP LH <i>pu</i>	1	\$ 712.00	\$ 712.00
7	REAR FENDER LH	1	\$ <i>pu</i> 1,025.00	\$ 1,025.00
8	REAR FENDER COWLING LH	1	\$ <i>pu</i> 212.00	\$ 212.00
9	REAR DOOR LH <i>pu/wrap</i>	1	\$ 1,258.00	\$ 1,258.00
10	REAR WHEEL BEARING LH	1	\$ 251.00	\$ 251.00
11	REAR BLINDSPORT SENSOR LH <i>pu</i>	1	\$ 1,125.00	\$ 1,125.00

TOTAL PRICE \$ 6,781.20
LESS 25% \$ 1,695.30
SUB TOTAL PRICE \$ 5,085.90

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR SPORT RIM LH <i>pu</i>	1	\$ 1,200.00	\$ 1,200.00
2	REAR TYRE LH	1	\$ <i>pu</i> 250.00	\$ 250.00
3	REAR DOOR STICKER LH	1	\$ <i>pu</i> 500.00	\$ 500.00
4	REAR BUMPER CLIPS	10	\$ <i>pu</i> 6.50	\$ 65.00
5	REAR BUMPER STICKER <i>pu</i>	1	\$ 150.00	\$ 150.00

TOTAL \$ 2,165.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$800.00	500l	
2	TO SPRAY PAINT AFFECTED AREA	\$1,000.00	800l	
3	REMOVE AND REFIX REAR UNDERCARRIAGE	na \$300.00	X	
4	CONDUCT WHEEL ALIGNMENT	\$150.00	60l	
5	TUFF COAT	\$250.00	30l	
6	WIRING CHECK	\$80.00	20l	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50l	

TOTAL

\$2,660.00

TOTAL PARTS COST : \$ 7,250.90
 TOTAL LABOUR COST : \$ 2,660.00
 TOTAL REPAIR COST : \$ 9,910.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: