

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24120296/Kvp3e2(N)
	16 RAFFLES QUA #42-01 HONG LEC 048581	Y ONG BUILDINGSINGAPORE	Date:	07/01/2025
	ATTN: SWEE KEC	NG	Code:	FCI2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHA 7008H	Veh. Inspected	SMV 3449A
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24011040MFCT	Excess (\$)	0.00
	Assign From	SWEE KEONG	Assign Date	19/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTDKB3FUX03092800	Colour	METALLIC PEARL WHITE
	Odometer	283892 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	TRIANGLE	9 mm
	TOTT TOTTE TYPE			
	L/H Front Tyre	195/65 R15	TRIANGLE	9 mm
			TRIANGLE TRIANGLE	9 mm 9 mm
	L/H Front Tyre	195/65 R15		-
4.	L/H Front Tyre R/H Rear Tyre	195/65 R15 195/65 R15 195/65 R15	TRIANGLE	9 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195/65 R15 195/65 R15 195/65 R15	TRIANGLE TRIANGLE on of Damages	9 mm 9 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195/65 R15 195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S	TRIANGLE TRIANGLE on of Damages	9 mm 9 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SU	195/65 R15 195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS.	TRIANGLE TRIANGLE on of Damages	9 mm 9 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SU	195/65 R15 195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS.	TRIANGLE TRIANGLE on of Damages FRONT PORTION AND U	9 mm 9 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SU	195/65 R15 195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS. General	TRIANGLE TRIANGLE On of Damages FRONT PORTION AND L Information Inspection Date	9 mm 9 mm UNDERCARRIAGE.
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDAMAGES SEE D Accident Date	195/65 R15 195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS. General 16/12/2024	TRIANGLE TRIANGLE On of Damages FRONT PORTION AND L Information Inspection Date	9 mm 9 mm UNDERCARRIAGE.
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDAMAGES SEE D Accident Date	195/65 R15 195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS. General 16/12/2024 MY CAR CONSULTANT PTE LT 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869	TRIANGLE TRIANGLE On of Damages FRONT PORTION AND L Information Inspection Date	9 mm 9 mm UNDERCARRIAGE.
5. 5a.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDAMAGES SEE D Accident Date Survey held at A)DAMAGES CONB)THE INSPECTION	195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS. General 16/12/2024 MY CAR CONSULTANT PTE LT 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 Resilistent to accident report ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	TRIANGLE TRIANGLE On of Damages FRONT PORTION AND LE Information Inspection Date TD Emarks T. HOUT PREJUDICE" BASILE HAVE NOT AUTHORISE	9 mm 9 mm INDERCARRIAGE. 19/12/2024
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUDAMAGES SEE D Accident Date Survey held at A)DAMAGES CONB)THE INSPECTION	195/65 R15 195/65 R15 Description STAINED DAMAGES AT THE N/S ETAILS. General 16/12/2024 MY CAR CONSULTANT PTE LT 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 Resilistent to accident report ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	TRIANGLE TRIANGLE On of Damages FRONT PORTION AND LE Information Inspection Date D Emarks T. HOUT PREJUDICE" BASILE HAVE NOT AUTHORISE Days of Repair	9 mm 9 mm INDERCARRIAGE. 19/12/2024