



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 5737896
HP: 93911482

Not Noted
L1 Ry &
Achieving After Paint
4-5 days

Estimation

Date:

19/12/2024

Vehicle:

SMV3449A

Make / Model:

TOYOTA PRIUS

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET	1	\$ 1,125.00	\$ 1,125.00
2	FRT BUMPER	1	\$ 879.00	\$ 879.00
3	FRT BUMPER SIDE RETAINER LH	1	\$ 45.00	\$ 45.00
4	FRT BUMPER SIDE GARNISH LH	1	\$ 112.00	\$ 112.00
5	FRT BUMPER LOWER	1	\$ 512.00	\$ 512.00
6	HEADLAMP LH	1	\$ 2,591.00	\$ 5,012.00
7	FRONT GRILLE	1	\$ 398.00	\$ 398.00
8	FRT HEADLAMP LOWER BRACKET LH	1	\$ 75.00	\$ 75.00
9	FRONT FENDER LH	1	\$ 698.00	\$ 698.00
10	FRONT FENDER EMBLEM LH	1	\$ 52.00	\$ 52.00
11	FRONT FENDER COWLING LH	1	\$ 169.00	\$ 169.00
12	FRONT FENDER TOP GARNISH LH	1	\$ 189.00	\$ 189.00
13	FRONT KNUCKLE ARM BEARING LH	1	\$ 198.00	\$ 198.00
14	FRONT KNUCKLE ARM LH	1	\$ 512.00	\$ 512.00
15	FRONT LOWER ARM LH	1	\$ 456.00	\$ 456.00
16	FRONT DOOR LH	1	\$ 1,125.00	\$ 1,125.00
	TOTAL PART			\$ 10,432.00
	LIST DOWN	25%		\$ 2,608.00
	AFTER LIST DOWN			\$ 7,824.00
SPECIAL NETT				
1	FRT BUMPER CLIP SET	1	\$ 50.00	\$ 50.00
2	FRONT SPORT RIM	1	\$ 600.00	\$ 600.00
3	FRONT WHEEL HUB CAP	1	\$ 100.00	\$ 100.00
4	FRT FENDER INNERSHIELD CLIP SET LH	1	\$ 50.00	\$ 50.00
	TOTAL AMOUNT			\$ 800.00
LABOUR				
1	CHECK WIRING	1	\$ 100.00	\$ 100.00
2	REMOVE AND REFIT FRONT UNDERCARRIAGE	1	\$ 300.00	\$ 300.00
3	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
4	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00
5	PANEL BEAT	1	\$ 600.00	\$ 600.00
6	SPRAY PAINTING	1	\$ 1,000.00	\$ 1,000.00
	TOTAL AMOUNT			\$ 2,240.00
Parts Replacement Amount				\$ 7,595.00
Total Amount for Labour				\$ 1,840.00
Total Amount				\$ 9,435.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurer's Company

Acknowledged by Repairer

Signature: _____

Date: _____

201
7
601
201
4001
5001