

T K LEE AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

SLC6191J

ESTIMATE

VEHICLE NO : PD1076P
MAKE/MODEL : TOYOTA HIACE
ACC DATE : 13.06.2024

Not Allowed
2/7/24
1/s \$1800
4 days
the ph. after up.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LIST PRICE			
1	1 REAR BUMPER	712.60	712.60
2	2 REAR BUMPER SIDE RETAINERS -R/L	48.60	97.20
3	1 REAR BUMPER SIDE BODY PANEL	1,762.50	1,762.50
4	1 REAR BUMPER SIDE BODY PANEL -CENTRE	1,251.90	1,251.90
5	1 REAR TAILLAMP -LH	481.33	481.33
6	1 REAR TAILLAMP LOWER GARNISH	126.32	126.32
7	1 SLIDING DOOR -LH	1,895.90	1,895.90
			6,327.75
		LESS 25%	1,581.94
			<u>4,745.81</u>

SPECIAL NETTS ITEM			
1	1 (SET) REAR BUMPER CLIP	50.00	50.00
2	1 (SET) REAR WHEEL HUB CAP	250.00	250.00
3	1 REAR STICKER 'EXCURSION BUS'	45.00	45.00
4	1 (SET) ADVERTISEMENT STICKER	220.00	220.00
			<u>565.00</u>

LABOUR CHARGES :			
1	TO CHECK REAR ELECTRICAL WIRING		40.00
2	TO REMOVE AND REFIX REVERSE SENSOR		60.00
3	TO TUFF KOTE		80.00
4	TO KNOCK, CUT/WELD AND REPLACE ACCIDENT PARTS		1,080.00
5	TO SPRAY PAINTING ON ACCIDENT PORTION		900.00
		TOTAL:	<u>2,160.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 7,470.81

P-1098.7
25%
824.03
300
1140
2264.03
202
1811.