



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg
Company Reg. No. 202341776E

TP INC
Veron

Vehicle No.: SMP450X
Make/Model : Toyota Harrier
Chassis no.: JTEZB3GH70J004745
Year of Manufacture : 2019

Date of survey:
Surveyor:
Company :
Ins Company : Income
TP vehicle No.: SLP2246T

Accident Date : 17 Dec 2024

Type of repair: Lump Sum

Estimate cost of repairs

Qty	Part Description	Unit Price	Total Price
1 pc	Tailgate <i>Dented</i>	\$ 2,175.00	\$ 2,175.00 ✓
1 pc	Tailgate inner trimboard <i>new</i>	\$ 661.00	\$ 661.00 ✓
1 pc	Tailgate glass moulding <i>new</i>	\$ 160.00	\$ 160.00 ✓
1 pc	Tailgate logo "Toyota" <i>new</i>	\$ 80.00	\$ 80.00 +
1 pc	Tailgate emblem "HARRIER" <i>new</i>	\$ 85.00	\$ 85.00 ✓
1 pc	Tailgate emblem "TURBO" <i>new</i>	\$ 55.00	\$ 55.00 ✓
1 pc	Rear bumper <i>Delud</i>	\$ 924.00	\$ 924.00 ✓
1 pc	Rear bumper lower garnish <i>Delud</i>	\$ 479.00	\$ 479.00 ✓
2 pcs	Reverse sensor <i>new</i>	\$ 503.00	\$ 1,006.00 <i>620</i>
1 pc	Rear end panel top garnish <i>new</i>	\$ 501.00	\$ 501.00 +
1 pc	Rear end panel <i>new</i>	\$ 1,260.00	\$ 1,260.00 ✓
			\$ 7,386.00
Less 25%			\$ (1,846.50)
			\$ 5,539.50

1 set	Rear bumper clips <i>new</i>	\$ 50.00 SN <i>30</i>
1 set	Tailgate trimboard clips <i>new</i>	\$ 50.00 SN +
1 set	Rear end panel top garnish clips <i>new</i>	\$ 50.00 SN +
1 set	Rear end panel sealant <i>new</i>	\$ 60.00 SN <i>X</i>
1 set	Tailgate windscreen sealant <i>new</i>	\$ 60.00 SN <i>30</i>
1 set	Tailgate windscreen cleaner <i>new</i>	\$ 40.00 SN <i>30</i>
1 set	Tailgate windscreen sponge <i>new</i>	\$ 40.00 SN <i>20</i>
		\$ 350.00

110



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhhbm.com.sg
Company Reg. No. 202341776E

1 job	To putty and spray painting	\$ 800.00	4w
1 job	Wiring Charges	\$ 60.00	30
1 job	To remove, refix reverse sensor	\$ 120.00	50
1 job	To remove, refix reverse camera	\$ 100.00	50
1 job	To remove, refix rear windscreen glass	\$ 120.00	✓
1 job	Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.	\$ 800.00	4w

\$ 2,000.00

Grand-total

\$ 7,889.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
2/s 20/12/24

042p-

Supplementary: 145.50

total: 4679

2/s: 3.7K ✓



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhhbm.com.sg
Company Reg. No. 202341776E

Vehicle No.: SMP450X
Make/Model : Toyota Harrier
Chassis no.: JTEZB3GH70J004745
Year of Manufacture : 2019

Date of survey:
Surveyor:
Company :
Ins Company : Income
TP vehicle No.: SLP2246T

Accident Date : 17 Dec 2024

Type of repair: Lump Sum

Supplementary

Qty	Part Description
1 pc	Rear bumper sponge

crushed

	Unit Price	Total Price
\$	194.00	\$ 194.00



Less 25%

\$	194.00
\$	(48.50)
\$	145.50

Adrian Ling,
HLG

194

less 25%: 145.50