



WEGA ENGINEERING

automotive workshop and beyond

Blk 176, Sin Ming Drive, #04-16, Sin Ming Autocare, Singapore 575721
TEL : 65-6452 149 FAX : 65-6452 9153 GST REG NO : 1999 00741 Z

Kenneth
20/12/24 96910663

NOT Authorized
L1 Imp & 6850/r
Running After Paim
10 2days

TO : Liberty Insurance Pte Ltd

VEHICLE ESTIMATE NO : TP 12/5212

One Raffles Quay,

DATE : 17-Dec-24

#25-01 North Tower,

VEHICLE NO : SLQ8994Y

Singapore 048583

MAKE / MODEL : TOYOTA WISH

Date of Accidents: 13/12/2024

REG YEAR : 2017

EMAIL : motorquotation@libertyinsurance.com.sg

CHASSIS NO : JTDGG20W70J007340

ATTN : MOTOR CLAIMS DEPT

Part Cost					
S/N	DESCRIPTION	QTY	Unit Price \$	AMOUNT \$	
1	BOOT LID PANEL SUB-ASSY 1400	1	\$2,263.80	\$2,263.80	✓
2	DOOR HINGE ASSY, RH	1	\$94.10	\$94.10	X
3	DOOR HINGE ASSY, LH	1	\$94.10	\$94.10	X
4	DOOR W/COURTESY LAMP SWITCH LOCK ASSY	1	\$628.80	\$628.80	X
5	DOOR LOCK STRIKER ASSY	1	\$56.70	\$56.70	X
6	DOOR STAY ASSY, RH	1	\$343.00	\$343.00	X
7	DOOR STAY ASSY, LH	1	\$343.00	\$343.00	X
8	BUMPER 593	1	\$911.60	\$911.60	✓
9	BUMPER CLIPS	1	\$5.50	\$5.50	✓
10	BUMPER SIDE RETAINER, RH	1	\$70.20	\$70.20	X
11	BUMPER SIDE RETAINER, LH	1	\$70.20	\$70.20	✓
12	BUMPER SIDE SUPPORT, RH	1	\$149.10	\$149.10	X
13	BUMPER SIDE SUPPORT, LH	1	\$149.10	\$149.10	✓
14	BUMPER EXTENSION, RH	1	\$92.50	\$92.50	X
15	BUMPER EXTENSION, LH	1	\$92.50	\$92.50	✓
16	BUMPER REFLECTOR, RH	1	\$83.40	\$83.40	X
17	BUMPER REFLECTOR, LH	1	\$83.40	\$83.40	✓
18	BUMPER REINFORCEMENT	1	\$343.00	\$343.00	X
19	BUMPER SKIRTING	1	\$94.10	\$94.10	X
20	REVERSE SENSOR SET	1	\$343.00	\$343.00	2000
21	TAILLAMP INTER, LH	1	\$602.00	\$602.00	✓
22	TAILLAMP OUTER, LH	1	\$452.40	\$452.40	✓
23	END PANEL 642	1	\$1,025.30	\$1,025.30	✓
24	END PANEL BOARD	1	\$413.40	\$413.40	X
25	END PANEL BOARD CLIPS	1	\$5.50	\$5.50	X
26	SPARE TYRE PANEL	1	\$1,115.40	\$1,115.40	X
27	SPARE TYRE PANEL BOARD (Centre) 780	1	\$999.00	\$999.00	X
28	SPARE TYRE PANEL BOARD (RH)	1	\$154.80	\$154.80	X
29	SPARE TYRE PANEL BOARD (LH)	1	\$154.80	\$154.80	X
30	SPARE TYRE PANEL BOARD CLIPS	1	\$5.50	\$5.50	X
31	REAR FENDER, LH 940	1	\$1,062.70	\$1,062.70	✓
32	REAR FENDER INNER BOARD, LH 785 Return	1	\$977.90	\$977.90	✓
33	REAR FENDER INNER BOARD CLIPS, LH	1	\$5.50	\$5.50	✓
34	FUEL FILLER OPENING LID ASSY	1	\$164.30	\$164.30	X
35	FUEL TANK CAP	1	\$114.10	\$114.10	X
36	FUEL TANK FILLER PIPE SHIELD ASSY	1	\$86.50	\$86.50	X
37	FUEL TANK FILLER PIPE SUB-ASSY	1	\$466.80	\$466.80	X
38	REAR DOOR PILLAR, LH	1	\$447.00	\$447.00	X
39	REAR DOOR PANEL SUB-ASSY, LH	1	\$2,393.90	\$2,393.90	X
40	DOOR CHECK ASSY, LH	1	\$303.00	\$303.00	X
41	DOOR UPPER HINGE, LH	1	\$137.10	\$137.10	X
42	DOOR LOWER HINGE, LH	1	\$137.10	\$137.10	X
43	DOOR HOOK, LH	1	\$59.20	\$59.20	X
44	DOOR LOCK, LH	1	\$802.20	\$802.20	X
45	WHEEL HOUSE BOARD (RH)	1	\$2,025.60	\$2,025.60	X
46	WHEEL HOUSE BOARD (RH)	1	\$999.00	\$999.00	X
46	WHEEL HOUSE BOARD (LH) Reported	1	\$999.00	\$999.00	X
Total Part Cost :				\$22,420.10	

257

Labour Cost

S/N	DESCRIPTION	QTY	Unit Price \$	AMOUNT \$
1	TO CHECK AND REPAIR WIRING OF TAILLAMP INTER & OUTER LH, REVERSE SENSOR & POWER WINDOW	1	\$800.00	\$800.00
2	TO REMOVE AND RENEW TAILLAMP INTER & OUTER LH, TAILLAMP INTER RH, LOGO EMBLEM, FUEL PUMP COVER AND REVERSE SENSOR	1	\$900.00	\$900.00
3	TO REPAIR, PANEL BEATING, REMOVE AND RENEW REAR END PANEL	1	\$1,000.00	\$1,000.00
4	TO REPAIR, PANEL BEATING, REMOVE AND RENEW SPARE TYRE PANEL	1	\$1,300.00	\$1,300.00
5	TO REPAIR, PANEL BEATING & DISMANTLE AND REPLACE REAR BUMPER	1	\$600.00	\$600.00
6	TO REPAIR, PANEL BEATING & DISMANTLE AND REPLACE BOOT LID	1	\$800.00	\$800.00
7	TO REPAIR, PANEL BEATING & DISMANTLE AND REPLACE REAR DOOR PANEL LH	1	\$500.00	\$500.00
8	TO REPAIR, PANEL BEATING & DISMANTLE AND REPLACE REAR FENDER LH	1	\$1,200.00	\$1,200.00
9	TO REPAIR, PANEL BEATING & DISMANTLE AND REPLACE REAR DOOR PILLAR LH	1	\$1,200.00	\$1,200.00
10	TO REPAIR, PANEL BEATING & DISMANTLE AND REPLACE REAR WHEEL HOUSE LH	1	\$1,200.00	\$1,200.00
11	TO REMOVE AND REFIT REAR WINDOW	1	\$200.00	\$200.00
12	TO REMOVE AND REFIT REAR WINDOW SEALANT	1	\$150.00	\$150.00
13	TO REMOVE AND REFIT SOLAR FLIM	1	\$200.00	\$200.00
14	TO REMOVE AND REFIT QUARTER WINDOW	1	\$200.00	\$200.00
15	TO PUTTY & RESPRAY REAR END PANEL	1	\$600.00	\$600.00
16	TO PUTTY & SPRAY PAINTING SPARE TYRE PANEL	1	\$800.00	\$800.00
17	TO PUTTY & SPRAY PAINTING REAR BUMPER, BOOT LID, REAR DOOR PANEL LH & REAR FENDER LH	1	\$800.00	\$800.00
Total Labour Cost :				\$12,450.00

Amount :	\$34,870.10
GST (9%) :	\$3,138.31
Grand Total :	\$38,008.41

ALL PRICES QUOTED ARE IN SINGAPORE DOLLAR AND SUBJECT TO 9% GST

Estimate prepared and authorised by:

Jeremy Goh
Executive

Wega Engineering Pte Ltd

Date: 13/12/2024

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



WEGA ENGINEERING

automotive workshop and beyond

51K 1/5, Sin Ming Drive, #04-16, Sin Ming Autocare, Singapore 575721
TEL: 65-6452 149 FAX: 65-6452 9153 GST REG NO: 1999 00741 Z

TO : Liberty Insurance Pte Ltd

One Raffles Quay,

#25-01 North Tower,

Singapore 048583

Date of Accidents: 13/12/2024

EMAIL : motorquotation@libertyinsurance.com.sg

ATTN : MOTOR CLAIMS DEPT

VEHICLE ESTIMATE NO : TP 12/5212

DATE : 23-Dec-24

VEHICLE NO : SLQ8994Y

MAKE / MODEL : TOYOTA WISH

REG YEAR : 2017

CHASSIS NO : JTDGG20W70J007340

Supplementary

Part Cost					
S/N	DESCRIPTION	QTY	Unit Price \$	AMOUNT \$	
1	BOOT LID RUBBER	1	\$363.80	\$363.80	
2	BOOT LID OUTSIDE GARNISH	1	\$413.40	\$413.40	
3	BOOT LID OUTSIDE GARNISH CLIPS	10	\$5.50	\$55.00	
4	BOOT LID GARNISH MOULDING, UPPER PROTECTOR	1	\$15.35	\$15.35	
5	BOOT LID GARNISH MOULDING, UPPER PROTECTOR	2	\$10.20	\$20.40	
6	BOOT LID GARNISH MOULDING, UPPER PROTECTOR RH	1	\$10.20	\$10.20	
7	BOOT LID GARNISH MOULDING, UPPER PROTECTOR LH	1	\$10.20	\$10.20	
8	BOOT LID 3M SOLAR FILM	1	\$200.00	\$200.00	
9	REAR FLOOR SIDE MEMBER SUB-ASSY LH	1	\$2,245.30	\$2,245.30	
9	DECK TRIM SIDE PANEL ASSY LH	1	\$1,115.40	\$1,115.40	
Total Part Cost :				\$4,449.05	

Labour Cost					
S/N	DESCRIPTION	QTY	Unit Price \$	AMOUNT \$	
1	TO REPAIR, PANEL BEATING REAR FLOOR SIDE MEMBER SUB-ASSY LH	1	\$800.00	\$800.00	
2	TO REMOVE AND REFIT BOOT LID ACCESSORIES AND ETC	1	\$400.00	\$400.00	
3	TO REFIT 3M SOLAR FILM	1	\$100.00	\$100.00	
Total Labour Cost :				\$1,300.00	

Amount :	\$5,749.05
GST (9%) :	\$517.41
Grand Total :	\$6,266.46

ALL PRICES QUOTED ARE IN SINGAPORE DOLLAR AND SUBJECT TO 9% GST

Estimate prepared and authorised by:

Jeremy Goh

Executive

Wega Engineering Pte Ltd

Date: 13/12/2024

Date: 13/12/2024