



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS3/INC24120306/Evh3e2
75 BRAS BASAH ROAD	Date:	20/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SJU 5625K	Veh. Inspected	FBK 7360H
Policy No.	-	Coverage	0
Claim No.	MT/1300552-003	Excess	\$0.00
Assign From	JULIE	Assign Date	28/11/2024

2. Vehicle Details

Make & Model	HARLEY DAVIDSON ROAD GLIDE	C.C	1690
Engine No.	KTMF698368	Year of Reg.	05/01/2016
Chassis No.	5HD1KTM C3FB698368	Colour	BLUE
Odometer	2442 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	120/70 R21	METZELER	5
L/H Front Tyre			
R/H Rear Tyre	180/55 R18	METZELER	5
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR O/S PORTION.

5. General Information

Accident Date	16/10/2024	Inspection Date	02/12/2024 (10:08)
Survey held at	MAKIMOTO - 25 KAKI BUKIT ROAD 4 #01-88, SYNERGY @ KAKI BUKIT SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.