

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 01.07.2024MODEL: Hyundai IoniqVEHICLE NO.: SHC1563A

SMF6888E

INSURANCE: SOMPO *45*MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper ?	1		\$ 459.40
	Rear Bumper Centre Moulding <i>Deland</i>	1		\$ 451.25
	Rear Bumper Lower Moulding <i>new</i>	1		\$ 155.00
	Rear Bumper Reinforcement ?	1		\$ 394.80
	Rear Bumper Rein-Brkt RH / LH ?	2	\$ 138.10	\$ 276.20
	Rear Bumper Clips <i>new</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper Tow Cover <i>new</i>	1		\$ 98.80
	Rear Bumper FogLamp ?	1		\$ 201.50
	Rear Smart Key Antenna ?	1		\$ 40.50
SUB TOTAL				\$ 2,099.45
LESS 25%				\$ 524.86
DISCOUNTED TOTAL				\$ 1,574.59
	Rear No.Plates With Trim Cover <i>Carld</i>	1		\$ 55.00
	Reverse Sensors ?	1		\$ 180.00
	Rear Bumper Mat <i>lit</i>	1		\$ 50.00
NETT TOTAL				\$ 285.00
SPARE PARTS TOTAL				\$ 1,859.59
<u>Labour Charge</u>				
Panel Beating				\$ 400.00
Spray Painting Charge				\$ 300.00
Remove/Refix Reverse Sensor				\$ 120.00
TOTAL LABOUR				\$ 820.00
ESTIMATE TOTAL				\$ 2,679.59

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
adrianling
@kkc-auto.com
2/5 01/09/24
02 Days.
4:15pm