## COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

DATE:

01.07.2024

**SMF6888E** 

MODEL:

Hyundai loniq

SOMPO CL INSURANCE:

VEHICLE NO .: SHC1563A

MVA: LIMTS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	0
	Rear Bumper	1	×	\$ 459.40	
	Rear Bumper Centre Moulding Welland	1		\$ 451.25	
	Pear Rumper Lower Moulding of W	1		\$ 155.00	+
	Rear Rumper Reinforcement	1		\$ 394.80	0
	Rear Bumper Rein-Brkt RH / LH	2	\$ 138.10	\$ 276.20	ā
	Rear Bumper Clips N~	10	\$ 2.20	\$ 22.00	
*	Rear Bumper Tow Cover Well ~	1		\$ 98.80	
7	Rear Bumper FogLamp wild	1		\$ 201.50	
	Rear Smart Key Antenna Trulld	1		\$ 40.50	
			1845.65	\$ 2,099.45	
e e	SUB TOTAL LESS 25%		416.41	\$ 524.86	
	DISCOUNTED TOTAL		1384.24	\$ 1,574.59	1
	DISCOURTED TOTAL		100101	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1
	4				
	Rear No.Plate With Trim Cover Culd	1		\$ 55.00	-
	Rear No. Plate With Trim Cover	1		\$ 180.00	
	Rear Bumper Mat	1		\$ 50.00	
	NETT TOTAL		105-00	\$ 285.00	1
	NETT TOTAL		100 00		1.
	SPARE PARTS TOTAL		1489.24	\$ 1,859.59	
)	Labour Charge				22-
	Panel Beating			\$ 400.00	380
	Spray Painting Charge			\$ 300.00 \$ 120.00	280
	Remove/Refix Reverse Sensor			\$ 120.00	50.
	TOTAL LABOUR		710-00	\$ 820.00	1
	*		2100 211	6 0 670 50	4
	ESTIMATE TOTAL	*	2199.24	\$ 2,679.59	+
'	estimate based on a visual inspection of the above vehicle. The fi	<u> </u>	l	ared after the	-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prep vehicle is surveyed by a motor Surveyor appointed by the insurance company.

\*Less 20% = 439.85