

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN SWAN GEK
BLK 230J TAMPINES ST 21 #12-669
SINGAPORE 523230

Contact : 97712466 84685081

TP Budget Direct
Xiao Chun.

TAX INVOICE

Repair Code : CLM16522

Date in : 19/12/2024

Vehicle Num. : SNQ354Z

Model : BYD DOLPHIN DYNAMIC

Chassis/Eng# : LC0CE4CC2P0482238/-

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET <i>Repair</i>	1	2800.00	X 2,800.00
FRONT BONNET MECHANISM LOCK <i>Not nee</i>	1	365.00	X 365.00
FRONT BUMPER <i>Deformed</i>	1	1790.00	1580 1,790.00
FRONT BUMPER CAMERA <i>Damaged</i>	1	900.00	✓ 900.00
FRONT BUMPER CAMERA HOLDER <i>nee</i>	1	150.00	✓ 150.00
FRONT BUMPER FOGLAMP GARNISH L/R (BLACK) <i>cut</i>	2	290.00	✓ 580.00
FRONT BUMPER INNER CENTER BRACKET <i>cracked</i>	1	280.00	✓ 280.00
FRONT BUMPER LOWER LID <i>cracked</i>	1	500.00	400 500.00
FRONT BUMPER LOWER LID MOULDING <i>cracked</i>	1	200.00	✓ 200.00
FRONT BUMPER NUMBER PLATE GARNISH <i>Damaged</i>	1	190.00	✓ 190.00
FRONT BUMPER PARKING SENSOR <i>2nd</i>	2	220.00	✓ 440.00
FRONT BUMPER SIDE MOULDING L/R (BLACK) <i>cut</i>	2	280.00	✓ 560.00
FRONT BUMPER SIDE RETAINER L/R <i>not nee</i>	2	65.00	X 130.00
FRONT BUMPER TOP GARNISH <i>cracked</i>	1	500.00	420 500.00
FRONT BUMPER TOW HOOK COVER <i>not nee</i>	1	60.00	X 60.00
FRONT BUZZLE SENSOR <i>Damaged</i>	1	325.00	✓ 325.00
FRONT CENTER LAMP <i>cracked</i>	1	1800.00	1580 1,800.00
FRONT GRILLE ASSY <i>lit</i>	1	800.00	✓ 800.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN SWAN GEK
 BLK 230J TAMPINES ST 21 #12-669
 SINGAPORE 523230

Contact : 97712466 84685081

TAX INVOICE

Repair Code : CLM16522

Date in : 19/12/2024

Vehicle Num. : SNQ354Z

Model : BYD DOLPHIN DYNAMIC

Chassis/Eng# : LC0CE4CC2P0482238/-

FRONT HEADLAMP L/R	<i>cracked</i>	2	3500.00	<i>660</i>	7,000.00
FRONT OUTSIDE TEMPERATURE SENSOR	<i>Damaged</i>	1	205.00	<i>✓</i>	205.00
FRONT SUPPORT PANEL	<i>Repair</i>	1	796.00	<i>X</i>	796.00
RADIATOR AIR VENT	<i>not new</i>	1	395.00	<i>X</i>	395.00
REAR BUMPER	<i>Distorted</i>	1	1680.00	<i>1400</i>	1,680.00
REAR BUMPER CAMERA	<i>Damaged</i>	1	1180.00	<i>✓</i>	1,180.00
REAR BUMPER LOWER DIFFUSER	<i>Deformed</i>	1	490.00	<i>✓</i>	490.00
REAR BUMPER LOWER DIFFUSER INNER BRACKET	<i>Deformed</i>	1	235.00	<i>✓</i>	235.00
REAR BUMPER LOWER LID (BLACK)	<i>Deformed</i>	1	850.00	<i>620</i>	850.00
REAR BUMPER NUMBER PLATE GARNISH	<i>Deformed</i>	1	180.00	<i>✓</i>	180.00
REAR BUMPER NUMBER PLATE LAMP L/R	<i>not new</i>	2	198.00	<i>X</i>	396.00
REAR BUMPER REFLECTOR L/R	<i>Cracked</i>	2	150.00	<i>✓</i>	300.00
REAR BUMPER REINFORCEMENT	<i>Dented</i>	1	890.00	<i>690</i>	890.00
REAR BUMPER REVERSE SENSOR	<i>3 pieces damaged</i>	4	220.00		880.00 <i>660</i>
REAR BUMPER REVERSE SENSOR HOLDER	<i>new</i>	4	30.00	<i>✓</i>	120.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>not new</i>	1	325.00	<i>X</i>	325.00
REAR BUMPER SIDE GARNISH L/R (BLACK)	<i>cut</i>	2	280.00	<i>490</i>	560.00
REAR BUMPER SIDE MOULDING L/R (BLACK)	<i>cut</i>	2	260.00	<i>460</i>	520.00

*** This is a computer-generated document which requires no signature. ***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN SWAN GEK
 BLK 230J TAMPINES ST 21 #12-669
 SINGAPORE 523230

Contact : 97712466 84685081

TAX INVOICE

Repair Code : CLM16522

Date in : 19/12/2024

Vehicle Num. : SNQ354Z

Model : BYD DOLPHIN DYNAMIC

Chassis/Eng# : LC0CE4CC2P0482238/-

REAR BUMPER SIDE RETAINER L/R	<i>Not new</i>	2	60.00	X	120.00
REAR END PANEL	<i>Distorted.</i>	1	1080.00	850 ✓	1,080.00
REAR END PANEL ANTENNA SENSOR	<i>Not new</i>	1	190.00	X	190.00
REAR END PANEL INNER TOP GARNISH	<i>Deformed</i>	1	250.00	✓	250.00
REAR FENDER INNER TRIM BOARD L/R	<i>LH Deformed</i>	2	596.00	596	1,192.00
REAR FLOOR PANEL	<i>Repair</i>	1	1120.00	X	1,120.00
REAR FLOOR PANEL SPONGE TRAY	<i>Cracked</i>	1	350.00	✓	350.00
REAR FLOOR PANEL TOP BOARD COVER	<i>Not new</i>	1	480.00	X	480.00
REAR TAILGATE	<i>Dented</i>	1	3800.00	3200 ✓	3,800.00
REAR TAILGATE 'BYD DOLPHIN' EMBLEM	<i>New</i>	1	115.00	✓	115.00
REAR TAILGATE HINGES L/R	<i>Not new</i>	2	125.00	X	250.00
REAR TAILGATE INNER TRIM BOARD	<i>Not new</i>	1	596.00	X	596.00
REAR TAILGATE LOCK STRIKER	<i>Not new</i>	1	60.00	X	60.00
REAR TAILGATE MECHANISM LOCK	<i>Damaged</i>	1	305.00	✓	305.00
REAR TAILGATE WEATHER STRIP	<i>Not</i>	1	325.00	✓	325.00
REAR TAILGATE WINDSCREEN MOULDING	<i>New</i>	1	205.00	✓	205.00
REAR TAILLAMP L/R	<i>LH Cracked</i>	2	976.00	976	1,952.00
					750

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN SWAN GEK
 BLK 230J TAMPINES ST 21 #12-669
 SINGAPORE 523230

Contact : 97712466 84685081

TAX INVOICE

Repair Code : CLM16522

Date in : 19/12/2024

Vehicle Num. : SNQ354Z

Model : BYD DOLPHIN DYNAMIC

Chassis/Eng# : LC0CE4CC2P0482238/-

		Subtotal before discount	28981	41,762.00
Percentage discount 10%			26082.90	4,176.20
		Sub-total 1		37,585.80
FRONT BUMPER CLIPS - SET	new	1	80.00	30 80.00
FRONT BUMPER NUMBER PLATE	3 damaged	1	25.00	✓ 25.00
FRONT BUMPER NUMBER PLATE HOLDER		1	50.00	30 50.00
REAR BUMPER CLIPS - SET	new	1	80.00	30 80.00
REAR BUMPER NUMBER PLATE	Best	1	25.00	✓ 25.00
REAR BUMPER NUMBER PLATE HOLDER	Deband	1	50.00	30 50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	new	1	50.00	20 50.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	new	2	50.00	30 100.00
REAR FLOOR PANEL INSULATOR MAT	new	1	300.00	x 300.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	new	1	50.00	x 50.00
REAR TAILGATE WINDSCREEN SEALANT	new	1	80.00	60 80.00
REAR TAILLAMP CLIPS L/R - SET	new	2	25.00	x 50.00
		Subtotal before discount		940.00
Percentage discount 0%				0.00
		Sub-total 2		940.00
		Parts-total		38,525.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN SWAN GEK
BLK 230J TAMPINES ST 21 #12-669
SINGAPORE 523230

Contact : 97712466 84685081

TAX INVOICE

Repair Code : CLM16522

Date in : 19/12/2024

Vehicle Num. : SNQ354Z

Model : BYD DOLPHIN DYNAMIC

Chassis/Eng# : LC0CE4CC2P0482238/-

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	✓ 80.00
To reset system after repair works	150 500.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓ 80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim gamish, trim liner carpet. (to FR)	60 100.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	800 1,300.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	400 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1200 2,200.00
To apply anti-rust chemical on repaired and replaced panel.	60 150.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
Labour Total	5,640.00
Parts & Labour Total	44,165.80

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 20/12/24

12 Days

total: 29372.50

L/S: 23 HK ✓