

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: SMB 1466T
Policy No. _____
Claims No. BUS/12/24/5032
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$30k
IDAC Accident Rpt Consistent? : Yes or No
GIA / PR Seen Consistent? : Yes or No
Est. Repairs: _____ vs Res.: Yes or No
Lum Sum: _____ 3 Val.: Yes or No
CA / REV _____
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SLL2978C Yr Regn: 2017, 82
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Vezel c.c. 1496
Colour: Bronze A/C: Insured / Std / NI / NA
Sp. Reading: 187735 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RU31215093
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 215/60R16
R: ~ ~
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Firenza
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 17/12/2024 D.O.I. 20/12/24
Survey held at LCR
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/2/25	LS \$3450 confirmed by email (Red 3981.28, 53%)

Date/Time, File Pass to? ☐ : Prell. Report
1) ☐ : Final Report
Date/Time, File Return to? _____
2) _____
Rep. Format: _____
Lump Sum / I.B.I. / _____

Days Of Repair: 5
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Invs (\$) _____
☐ : Weekend (\$) _____

Survey Fee: _____
Transportation: _____
S + RS. \$ _____
Photos _____
Others _____
TOTAL _____



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

MS First Capital Insurance Ltd
Date : 18/12/2024
Attn : Motor Claim Department

ESTIMATE

Vehicle Number : SLL2998C
Make & Model : HONDA VEZEL HYBIRD
Chassis Number : RU31215093
Registration Date : 07/03/2017
Date Of Accident : 17/12/2024 14:00
3rd Party Vehicle No. : SMB1466T

PARTS DISCRPTION	QTY	UNIT PRICE	LIST PRICE
		\$S	\$S
1 TAILGATE	1	\$ 1,068.10	\$ 1,068.10 <i>bt</i>
2 TAILGATE 'LOGO' EMBLEM	1	\$ 24.80	\$ 24.80 <i>re</i>
3 TAILGATE 'VEZEL' EMBLEM	1	\$ 58.50	\$ 58.50 <i>re</i>
4 TAILGATE 'HYBIRD' EMBLEM	1	\$ 61.20	\$ 61.20 <i>re</i>
5 TAILGATE MECHANISM LOCK	1	\$ 95.70	\$ 95.70 <i>X nn</i>
6 TAILGATE INNER TRIM BOARD	1	\$ 547.00	\$ 547.00 <i>X nn</i>
7 TAILGATE WEATHERSTRIP	1	\$ 105.20	\$ 105.20 <i>X nn</i>
8 TAILGATE REFLECTOR LAMP RH	1	\$ 449.40	\$ 449.40 <i>an</i> 350
9 TAILLAMP RH	1	\$ 486.70	\$ 486.70 <i>an</i>
10 REAR BUMPER TOP RH	1	\$ 482.00	\$ 482.00 <i>de</i> 290
11 REAR BUMPER LOWER	1	\$ 1,128.00	\$ 1,128.00 <i>de</i> 780
12 REAR BUMPER SIDE RETAINER RH	1	\$ 72.00	\$ 72.00 <i>X nn</i>
13 REAR BUMPER REFLECTOR RH	1	\$ 75.00	\$ 75.00 <i>cut</i>
14 REAR END PANEL	1	\$ 762.00	\$ 762.00 <i>Rp</i>
15 REAR END PANEL TOP GARNISH	1	\$ 261.00	\$ 261.00 <i>X nn</i>
		LIST TOTAL \$S:	\$ 5,676.60
		20.00% DISCOUNT \$S:	\$ 1,135.32
			\$ 4,541.28

3194.30
2555.44

SPECIAL NETT	QTY	UNIT PRICE	AMOUNT
1 TAILGATE GLASS SEALANT WITH PRIMER SET	1	\$ 60.00	\$ 60.00 ✓
2 TAILGATE INNER TRIM BOARD CLIPS SET	1	\$ 40.00	\$ 40.00 <i>X nn</i>
3 TAILLAMP INNER PANEL SEALANT	1	\$ 60.00	\$ 60.00 <i>X nn</i>
4 REAR BUMPER CLIPS SET	1	\$ 50.00	\$ 50.00 <i>30w</i>
5 REVERSE SENSOR	1	\$ 280.00	\$ 280.00 <i>cut - 200</i>
6 REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00 <i>X nn</i>
7 REAR END PANEL TOP GARNISH CLIPS SET	1	\$ 40.00	\$ 40.00 <i>X nn</i>
		SPECIAL NETT TOTAL \$S:	\$ 630.00

290

LABOUR CHARGES

1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	\$ 800.00	600
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	\$ 800.00	600
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	\$ 120.00	30
4	TO REMOVE AND REFIX/REPLACE REAR TRIMS, GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	\$ 180.00	60
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 120.00	30
6	TO REMOVE AND REPLACE REVERSE SENSORS	\$ 120.00	30
7	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	\$ 120.00	✓

LABOUR TOTAL S\$: \$ 2,260.00 1470

TOTAL S\$: \$ 7,431.28

9% GST: \$ 594.50

GRAND TOTAL S\$: \$ 8,025.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749/62563561
 up 20/12/24 @ 1150
 4/5 Ready after repair
 Taufik taufik@lkkauto.com
 5 days

2555.44
 290
 1470
 4315.44
 LS\$3450
 5 DAYS #