ESTIMATED ACCIDENT REPAIR COST



9% GST

PARTS TOTAL COST

396.00

35.20

38.81

470.01

\$

			Co. / GS	ST Reg No. 201419417K
ACCIDENT TIME REPORTED	15:42	BUS REGISTRATION NUMBER	SBS6	307C
ACCIDENT DATE	18-Dec-24	BUS TYPE (SD/DD)	S	D
BUS CAPTAIN NAME	CHAN WEN JIAT	BUS ROUTE NO.		
THIRD PARTY CLAIM AGAINST	SMRT	BUS ADVERT (Y/N)	יו	V
SECTION 1 : P	PARTS & CONSUMABLE ITEMS (MA	TERIAL COST)		
NO.	Part or Item De	scription	Quantity	Total Cost
1	GLASS PANE	W. Lo.	4	¢ 306.00

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

SIKAFLEX BLACK

2

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TOTAL COST	
TO DISMANTLE & REPLACE :-				
DISMANTLE AND REPLACE ITEM NO :1-2		650	\$	1,300.00
SPRAY PAINTING \$640 PER PANEL	(50	9% GST	\$	117.00
LABOUR CHARGES \$650 PER DAY	6,5	LABOUR TOTAL COST	\$	1,417.00

10%-388.08

the Repairer of the following: • To resurvey before/after spray painting	US IN WORKSHOP FOR SURVEY &	REPAIRS	
To display damaged part(s) during resurvey		DATE IN	18/Dec/2024
Parts prices are subject to confirmation Third party survey is on a "Without Prejudice"	basis	DATE & TIME SURVEY	
 No illegal modification(s) is allowed 		DATE OUT	
Supplementary item(s) must be resurveyed at subject to final approval from Insurance Cor	BUS TYPE SD SD	TOTAL NUMBER OF DAYS	1
owiedged by Repairer	LOSS OF USE COST	\$300.0	0
1.45		*	

Taythi 97495749

WP 73/12/248/145

PIP Rosum, new part father repaired 1038.08

tautim elhhantorium

Olday

SUMMARY				
SECTION NO.		COST		
1	\$	470.01		
2	\$	1,417.00		
3	\$	300.00		
TOTAL	\$	2,187.01		

PAGE 1