

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Authorised
air
means
3/1/25
1/5 \$ 4500
4 days

VEHICLE No: SKW 544X

1PC	REAR WINDSCREEN	new	\$1,488.10	x
1PC	REAR WINDSCREEN MOULDING	new	\$188.30	—
1PC	TAILGATE	bodywork	\$2,185.10	—
1PC	TAILGATE REAR LOGO	src	\$68.50	x
1PC	TAILGATE 'HARRIER' EMBLEM	new	\$96.80	—
1PC	TAILGATE WEATHERSTRIP	src	\$418.90	x
1PC	TAILGATE INNER LOCK	Door/motion	\$441.90	—
1PC	TAILGATE INNER TRIM	De/trim	\$611.60	—
2PCS	TAILGATE INNER DAMPERS @535.10	src	\$1,070.20	x
1PC	REAR BUMPER	De	\$866.00	—
1PC	REAR BUMPER CENTRE BLACK GARNISH	De	\$488.90	—
2PCS	REAR BUMPER REFLECTORS @\$85.00	new	\$170.00	x
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	new	\$130.00	x
1PC	REAR BUMPER SPONGE	bodywork	\$199.80	—
1PC	REAR END PANEL OUTER	new	\$899.10	x
1PC	REAR END PANEL LOCK SENSOR	new	\$350.00	x
1PC	REAR END PANEL TOP GARNISH	src	\$468.90	x
2PCS	TAILLAMPS @\$650.50	new	\$1,301.00	x
			\$11,443.10	
LESS 25%			\$8,582.33	

S.NETT

1SET	REAR BUMPER CLIPS	new	\$50.00	30
1PC	REAR WINDSCREEN SEALANT	new	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	new	\$50.00	20
1PC	REAR END PANEL SEALANT	new	\$50.00	x
1SET	TAILGATE INNER TRIM CLIPS	new	\$50.00	30
1SET	REAR BUMPER REVERSE SENSOR	motion	\$200.00	200
TO CHECK WIRING			\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR			\$80.00	40
TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$120.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM			\$100.00	x
TO DISMANTLE & REFIX REAR EXHAUST			\$100.00	x
TO TRANSFER TAILGATE MECHANISM			\$100.00	80
TO SPRAY PROOFING			\$180.00	30
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,000.00	550

TO PUTTY & SPRAY PAINTING

TOTAL \$1,500.00 600
\$12,412.33

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5078-4
252
380880
320
1500
562880
222
4503