

CD/LPC 24120311/Dpa³

ASSIGNMENT

COE 22/04/2032

From: _____ Date: _____
 Estimated Cost: _____
 OB / TP / NS / TP RES / CD RES / EVA / SN / MV
 To inspect Vehicle No: _____
 at Workshop in/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 G/A / PR Spec: _____ Consistent? : Yes or No
 Est. Repair: 48 days Res: Yes or No
 Lump Sum: PIP % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 2554 U Yr Reg: 23/04/2024
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 1580
 Make: Hyundai Kona CC: 2448
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 57838 T/Radio: Insured / Std / NI / NA
 Eng No: G4LLRU 406006
 C/No: KMH B811V R U053654
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / SRim / STD ARim or

Tyre Size: F: 205/65 R16
 R: 11

ES / DUN / EXOVA / GY / FS / LZA / M/C / OHSU / PR / SUMI /
 TOYO / YOKO or Kumho

Front Rear
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 19/12/2024 D.O.I: 20/12/2024

Survey held at: First Wynd
 Des. of Damages: Fnt / Rear / O/S / N/S / M/C / Roofing or

Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>WNPAL YN 4584K</u>
<u>18/3/23</u>	<u>primary PIP 11,289.96 with 8 dgs of rep</u>

Days of Repair: _____
 Resurvey No. of Trip: _____

Days of Repair: _____
 Resurvey No. of Trip: _____

Report Format: _____
 Lump Sum / L.B. (\$) _____

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee:	
Transporter:	
S-RS	
Photos	
Other	
TOTAL	

REPAIR ESTIMATE

longer

DESCRIPTION	QTY	LIST PRICE	AMOUNT
COVER ASSY-RR BUMPER <i>broken</i>	1	\$ 1,015.00	\$ 1,015.00
DIFFUSER ASSY-RR BUMPER <i>broken</i>	1	\$ 856.70	\$ 856.70
BRACKET ASSY-RR BUMPER LWR,(LH/RH) <i>HL</i>	2	\$ 32.00	\$ 64.00
CAP-RR HOOK <i>SVC</i>	1	\$ 41.00	\$ 41.00
BRACKET-RR BUMPER SIDE MTG,(LH/RH) <i>HL</i>	2	\$ 22.00	\$ 44.00
BEAM-REAR BUMPER <i>broken</i>	1	\$ 582.00	\$ 582.00
STAY-RR BUMPER,(LH/RH) <i>HL</i>	2	\$ 55.00	\$ 110.00
BRACKET ASSY-RR BUMPER SD UPR,(LH/RH) <i>HL</i>	2	\$ 35.00	\$ 70.00
COVER ASSY-RR BUMPER UPR,(LH/RH) <i>O/S monthly broken</i>	2	\$ 201.00	\$ 402.00
PARKING SENSOR <i>SVC</i> <i>W/S HL</i>	4	\$ 262.00	\$ 1,048.00
PARKING SENSOR WIRE <i>HL</i>	1	585.35	\$ 585.35
PANEL ASSY-TAIL GATE <i>Reman</i>	1	\$ 2,164.00	\$ 2,164.00
HINGE ASSY-TAIL GATE (LH/RH) <i>HL</i>	2	\$ 28.00	\$ 56.00
TRIM ASSY-TAIL GATE LWR <i>HL</i>	1	\$ 378.00	\$ 378.00
TRIM ASSY-TAIL GATE UPR <i>HL</i>	1	\$ 63.00	\$ 63.00
TRIM ASSY-TAIL GATE FRAME SIDE (LH/RH) <i>HL</i>	2	\$ 39.00	\$ 78.00
BUMPER-T/GATE SIDE GUIDE <i>HL</i>	2	\$ 16.00	\$ 32.00
W/STRIP-TAIL GATE OPNG <i>SVC</i>	1	\$ 137.00	\$ 137.00
LATCH ASSY-TAIL GATE <i>Done</i>	1	\$ 278.00	\$ 278.00
STRIKER ASSY-T/GATE <i>HL</i>	1	\$ 25.00	\$ 25.00
HANDLE ASSY-TAIL GATE O/S <i>HL</i>	1	\$ 125.00	\$ 125.00
LIFTER ASSY-TAIL GATE,(LH/RH) <i>HL</i>	2	\$ 111.00	\$ 222.00
BOOT TOP COVER CTR <i>HL monthly broken</i>	1	\$ 455.00	\$ 455.00
BOOT EMBLEM-SYMBOL MARK <i>HL</i>	1	\$ 72.00	\$ 72.00
EMBLEM-KONA <i>HL</i>	1	\$ 97.00	\$ 97.00
EMBLEM-HYBRID <i>HL</i>	1	\$ 47.00	\$ 47.00
GLASS ASSY-TAIL GATE <i>Shattered</i>	1	\$ 609.00	\$ 609.00
SPOILER-RR <i>HL</i>	1	\$ 1,347.00	\$ 1,347.00
COVER-RR SPOILER <i>HL</i>	2	\$ 14.00	\$ 28.00
GARNISH ASSY-TAIL GATE <i>Reman HL</i>	1	\$ 375.00	\$ 375.00
REAR SPARE TYRE TOP COVER <i>HL</i>	1	\$ 650.40	\$ 650.40
3RD BRAKE LAMP ASSY-CENTER POSITION <i>broken</i>	1	\$ 6,604.00	\$ 6,604.00
LAMP ASSY-REAR COMB OUTSIDE <i>O/S cut W/S HL</i>	2	\$ 717.00	\$ 1,434.00
LAMP ASSY-REAR COMB,LWR <i>O/S cracked W/S HL</i>	2	\$ 953.00	\$ 1,906.00
LAMP ASSY-REAR FOG <i>broken</i>	1	\$ 163.00	\$ 163.00
ARM ASSY-RR WIPER <i>HL</i>	1	\$ 106.00	\$ 106.00
MOTOR & LINKAGE ASSY-REAR WPR <i>HL</i>	1	\$ 352.00	\$ 352.00
UNIT ASSY-REAR VIEW CAMERA <i>HL</i>	1	\$ 1,088.00	\$ 1,088.00

J J x x x J x x J x x x x x J x x x J J J J x x x x x J f f f J x x x

1306.00

RR FENDER INNER TRIM,(LH/RH) <i>o/s broken 4/5mm</i>	2	\$ 1,439.00	\$ 2,878.00
DUCT ASSY-RR VENT <i>HH</i>	2	\$ 75.00	\$ 150.00
UNIT ASSY-REAR CORNER RADAR,(LH/RH) <i>HH</i>	2	\$ 1,268.00	\$ 2,536.00
PANEL ASSY-UNDER COVER <i>HH</i>	1	\$ 221.00	\$ 221.00
MUFFLER ASSY-REAR <i>HH</i>	1	\$ 1,341.00	\$ 1,341.00
HANGER-EXHAUST PIPE <i>HH</i>	2	\$ 11.00	\$ 22.00
REAR END PANEL <i>Rear</i>	1	\$ 729.00	\$ 729.00
REAR END PANEL GARNISH <i>minty broken</i>	1	\$ 190.00	\$ 190.00
PANEL COMPLETE-REAR TYRE <i>HH</i>	1	\$ 5,139.00	\$ 5,139.00
			\$ -
SUB TOTAL			\$ 35,043.75
LESS 20%			\$ 7,008.75
DISCOUNTED TOTAL			\$ 28,035.00
COMFORT LOGO <i>HH</i> SN	1	\$ 80.00	\$ 80.00
REAR WINDSCREEN SEALANT <i>HH</i> SN	1	\$ 46.00	\$ 46.00
REAR NUMBER PLATE <i>CRACK</i> SN	1	\$ 45.00	\$ 45.00
SUB TOTAL			\$ 171.00
Labour Charge			
Panel Beating	1	\$ 2,200.00	\$ 2,200.00
Spray Painting Charge	1	\$ 1,600.00	\$ 1,600.00
Wiring Charge	1	\$ 100.00	\$ 100.00
Tuff Kote	1	\$ 100.00	\$ 100.00
Towing Charge	1	\$ 80.00	\$ 80.00
Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$ 150.00
Remove/Refix Rear Windscreen Glass	1	\$ 120.00	\$ 120.00
Remove/Refix Exhaust Pipe	1	\$ 80.00	\$ 80.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$ 550.00
TOTAL LABOUR			\$ 4,980.00
ESTIMATE TOTAL			\$ 33,186.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

11,873.70
9498.96

171.00

800/-
800/- 600/-
30/-
30/-
80/-
80/-
HH
HH

1620.00

20/12/2024 @ 1600w P/P 11,289.96

NA Arthur
P/P 8 days

ign
Photo after repair
2 KKK Auto with damaged parts.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC2554U
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	SX2 KONA 1.6 GDI HEV
Primary Colour:	Blue
Manufacturing Year:	2024
Engine No.:	G4LLRU406006
Chassis No.:	KMHHB811VRU053654
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$25,348.00
Original Registration Date:	23 Apr 2024
First Registration Date:	23 Apr 2024
Transfer Count:	0
Actual ARF Paid:	\$19,988.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Apr 2032
PARF Rebate Amount:	\$14,991.00
Intended COE Rebate Details	
COE Expiry Date:	22 Apr 2032
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	8
PQP Paid:	\$62,786.00
COE Rebate Amount:	\$57,379.00
Total Rebate Amount:	\$72,370.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Dec 2024

OK