



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2505134

INV Date 05/08/2025

Reference CD/LPC24120312/Tpa3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 1244A  
Insured Veh. YR 1071Y  
Claim No. 24/24/25/VC05/030335  
Policy No. Z24VC05026909  
Accident Date 14/12/2024  
Inspection Date 26/12/2024

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 450.00        |
| <b>Subtotal</b>                | <b>450.00</b> |
| <b>GST (9%)</b>                | <b>40.50</b>  |
| <b>Grand Total</b>             | <b>490.50</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                 |                                                                                                                                        |                                                                                                        |                               |            |
|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-------------------------------|------------|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555 |                                                                                                                                        |                                                                                                        | Ref: CD/LPC24120312/Tpa3q2(N) |            |
|                                                                                   |                                                                                                                                        |                                                                                                        | Date: 05/08/2025              |            |
|                                                                                   |                                                                                                                                        |                                                                                                        | Code: LPC2                    |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                 |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   | Insured Veh.                                                                                                                           | YR 1071Y                                                                                               | Veh. Inspected                | SMJ 1244A  |
|                                                                                   | Policy No.                                                                                                                             | Z24VC05026909                                                                                          | Coverage (\$)                 | 0.00       |
|                                                                                   | Claim No.                                                                                                                              | 24/24/25/VC05/030335                                                                                   | Excess (\$)                   | 0.00       |
|                                                                                   | Assign From                                                                                                                            | ERIC                                                                                                   | Assign Date                   | 26/12/2024 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                     |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   | Make & Model                                                                                                                           | KIA CERATO                                                                                             | c.c                           | 1591       |
|                                                                                   | Engine No.                                                                                                                             | HIDDEN                                                                                                 | Year of Reg.                  | 2019       |
|                                                                                   | Chassis No.                                                                                                                            | KNAF3416MK5030683                                                                                      | Colour                        | GREY       |
|                                                                                   | Odometer                                                                                                                               | 72940 KM                                                                                               | Steering                      | IN ORDER   |
|                                                                                   | Brakes                                                                                                                                 | IN ORDER                                                                                               | Modification                  | SPORTS RIM |
|                                                                                   | General                                                                                                                                | GOOD                                                                                                   |                               |            |
| <b>3. Conditions of Tyres</b>                                                     |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   |                                                                                                                                        | Size                                                                                                   | Make                          | Balance    |
|                                                                                   | R/H Front Tyre                                                                                                                         | 205/55 R16                                                                                             | YOKOHAMA                      | 6 mm       |
|                                                                                   | L/H Front Tyre                                                                                                                         | 205/55 R16                                                                                             | YOKOHAMA                      | 6 mm       |
|                                                                                   | R/H Rear Tyre                                                                                                                          | 205/55 R16                                                                                             | YOKOHAMA                      | 6 mm       |
|                                                                                   | L/H Rear Tyre                                                                                                                          | 205/55 R16                                                                                             | YOKOHAMA                      | 6 mm       |
| <b>4. Description of Damages</b>                                                  |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br><br>DAMAGES SEE DETAILS.                                               |                                                                                                        |                               |            |
| <b>5. General Information</b>                                                     |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   | Accident Date                                                                                                                          | 14/12/2024                                                                                             | Inspection Date               | 26/12/2024 |
|                                                                                   | Survey held at                                                                                                                         | WAH HONG MOTORS & CREDIT PTE LTD<br>38 TOH GUAN ROAD EAST<br>#01-57 ENTERPRISE HUB<br>SINGAPORE 608581 |                               |            |
| <b>5a. Remarks</b>                                                                |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                        |                               |            |
| <b>5b. Estimate Days of Repair</b>                                                |                                                                                                                                        |                                                                                                        |                               |            |
|                                                                                   | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                        | 9 Working Days                |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 1244A

| Qty | Description of Parts                      | Condition                       | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------|---------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>        |                                 |                           |                   |
| 1   | BONNET                                    | BENT                            | 1,610.00                  | 1,610.00          |
| 2   | BONNET HINGE RH/LH @\$38.00               | BENT                            | 76.00                     | 76.00             |
| 1   | BONNET INSULATOR                          | DEFORMED                        | 141.00                    | 141.00            |
| 1   | BONNET LOCK                               | NOT NECESSARY                   | 93.00                     | -                 |
| 2   | HEADLAMP RH /LH @\$1221.00                | O/S NOT NECESSARY / N/S CRACKED | 2,442.00                  | 1,221.00          |
| 1   | FRONT BUMPER                              | DEFORMED                        | 634.00                    | 634.00            |
| 2   | FRONT BUMPER SIDE RETAINER LH/RH @\$20.00 | NOT NECESSARY                   | 40.00                     | -                 |
| 1   | FRONT BUMPER LOGO BADGE                   | CUT                             | 25.00                     | 25.00             |
| 1   | CENTER GRILLE                             | CRACKED                         | 296.00                    | 296.00            |
| 1   | RADIATOR TOP GARNISH                      | CRACKED                         | 35.00                     | 35.00             |
| 1   | FRONT BUMPER SPONGE                       | NOT NECESSARY                   | 76.00                     | -                 |
| 1   | FRONT REINFORCEMENT                       | NOT NECESSARY                   | 449.00                    | -                 |
| 2   | RADIATOR SIDE AIR GUIDE RH/LH @\$25.00    | NOT NECESSARY                   | 50.00                     | -                 |
| 1   | SUPPORT PANEL                             | NOT NECESSARY                   | 609.00                    | -                 |
| 1   | CONDENSER                                 | NOT NECESSARY                   | 620.00                    | -                 |
| 1   | RADIATOR                                  | NOT NECESSARY                   | 583.00                    | -                 |
| 1   | FAN COWLING ASSY                          | NOT NECESSARY                   | 592.00                    | -                 |
| 1   | DUCT EXTENSION                            | NOT NECESSARY                   | 5.00                      | -                 |
| 1   | AIR INTAKE SHIELD                         | NOT NECESSARY                   | 8.00                      | -                 |
| 1   | AIR DUCT                                  | NOT NECESSARY                   | 49.00                     | -                 |
| 1   | BOOT LID                                  | BENT                            | 1,298.00                  | 1,298.00          |
| 2   | BOOT LID HINGE LH/RH @\$88.00             | TO REPAIR SEE LABOUR            | 176.00                    | -                 |
| 1   | BOOT LID LOGO BADGE                       | NECESSARY                       | 29.00                     | 29.00             |
| 1   | BOOT LID EMBLEM CERATO                    | NECESSARY                       | 25.00                     | 25.00             |
| 1   | BOOT LID WEATHERSTRIP                     | TWISTED                         | 90.00                     | 90.00             |
| 1   | BOOT LID LOCK                             | NOT NECESSARY                   | 101.00                    | -                 |
| 2   | BOOT LID LAMP LH/RH @\$549.00             | CUT                             | 1,098.00                  | 1,098.00          |
| 1   | BOOT LID CENTER GARNISH LAMP              | CUT                             | 623.00                    | 623.00            |
| 2   | TAIL LAMP LH/RH @\$609.00                 | CUT                             | 1,218.00                  | 1,218.00          |

Report Ref No. CD/LPC24120312/Tpa3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                            | Condition                        | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------|----------------------------------|---------------------------|-------------------|
| 1   | REAR BUMPER                                     | DEFORMED                         | 652.00                    | 652.00            |
| 2   | REAR BUMPER SIDE RETAINER LH/RH @\$28.00        | N/S DEFORMED / O/S NOT NECESSARY | 56.00                     | 28.00             |
| 1   | REAR FOG LAMP LH                                | NOT NECESSARY                    | 163.00                    | -                 |
| 1   | REAR FOG LAMP COVER LH                          | CUT                              | 17.00                     | 17.00             |
| 1   | REAR REVERSE SENSOR @\$62.00                    | NOT WORKING                      | 124.00                    | 124.00            |
| 1   | REAR BUMPER LOWER GARNISH                       | DEFORMED                         | 218.00                    | 218.00            |
| 1   | REAR BUMPER LOWER COVER LH                      | NOT NECESSARY                    | 30.00                     | -                 |
| 1   | REAR REINFORCEMENT                              | CRACKED                          | 287.00                    | 287.00            |
| 2   | REAR REINFORCEMENT BEAM RH/LH @\$59.00          | BENT                             | 118.00                    | 118.00            |
| 2   | REAR REINFORCEMENT BRACKET RH/LH @\$8.00        | NOT NECESSARY                    | 16.00                     | -                 |
| 2   | REAR REINFORCEMENT CENTER BRACKET RH/LH @\$6.00 | NOT NECESSARY                    | 12.00                     | -                 |
| 1   | END PANEL TOP GARNISH                           | NOT NECESSARY                    | 37.00                     | -                 |
| 2   | FRONT FENDER RH/LH (NPA)                        | TO REPAIR SEE LABOUR             | -                         | -                 |
| 2   | REAR FENDER RH/LH (NPA)                         | TO REPAIR SEE LABOUR             | -                         | -                 |
| 1   | END PANEL (NPA)                                 | TO REPAIR SEE LABOUR             | -                         | -                 |
| 1   | FLOOR PANEL (NPA)                               | TO REPAIR SEE LABOUR             | -                         | -                 |
|     | LESS 10% DISCOUNT                               |                                  | -1,482.10                 | -986.30           |
|     |                                                 |                                  | 13,338.90                 | 8,876.70          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                |                                  |                           |                   |
| 1   | BONNET INSULATOR CLIPS (SN)                     | NOT NECESSARY                    | 25.00                     | -                 |
| 1   | FRONT BUMPER CLIPS (SN)                         | NECESSARY                        | 35.00                     | 35.00             |
| 1   | CENTER GRILLE CLIPS (SN)                        | NECESSARY                        | 25.00                     | 25.00             |
| 1   | FRONT CAR PLATE WITH HOLDER (SN)                | CUT                              | 35.00                     | 35.00             |
| 1   | RADIATOR TOP GARNISH CLIPS (SN)                 | NECESSARY                        | 25.00                     | 25.00             |
| 1   | COOLANT (SN)                                    | NOT NECESSARY                    | 50.00                     | -                 |
| 1   | BOOT LID EMBLEM CC (SN)                         | NECESSARY                        | 100.00                    | 100.00            |
| 1   | REAR CAR PLATE WITH HOLDER (SN)                 | NOT NECESSARY                    | 35.00                     | -                 |
| 1   | REAR BUMPER CLIPS (SN)                          | NECESSARY                        | 35.00                     | 35.00             |

Report Ref No. CD/LPC24120312/Tpa3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                         | Description of Parts                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1                           | REAR BUMPER LOWER GARNISH CLIPS (SN)<br><br><u>LABOUR</u><br><br>TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF BOOT LID HINGE LH/RH,FRONT FENDER RH/LH ,REAR FENDER RH/LH,END PANEL AND FLOOR PANEL.<br><br>TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.<br><br>TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.<br><br>REMOVE AND REFIT AIRCON CONDENSER ,RADIATOR ,RELATED PIPES AND HOSES, VACUUM AND REFILL AIRCON GAS. | NECESSARY | 30.00                     | 30.00             |
|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |           | 395.00                    | 285.00            |
|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |           | 1,800.00                  | 1,200.00          |
|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 2,000.00  | 1,800.00                  |                   |
|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 60.00     | 40.00                     |                   |
|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 100.00    | -                         |                   |
|                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 3,960.00  | 3,040.00                  |                   |
| GRAND TOTAL                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |           | 17,693.90                 | 12,201.70         |
| RECOMMENDED COST OF REPAIRS |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |           |                           | 12,201.70         |

Report Ref No. CD/LPC24120312/Tpa3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 1244A

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 1244A

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

