



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMJ1244A KIA CERATO 1.6(A) EX

Page No. 1-1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet		1610.00	bt
2	Bonnet hinge RH/LH@2*\$38		76.00	bt
1	Bonnet insulator		141.00	de
1	Bonnet lock		93.00	un
2	Headlamp RH/LH@2*\$1221		2442.00	RHX, LH 1221
1	Front bumper		634.00	de
2	Front bumper side retainer RH/LH@2*\$20		40.00	un
1	Front bumper logo badge		25.00	cut
1	Center grille		296.00	cut
1	Radiator top garnish		35.00	cut
1	Front bumper sponge		76.00	un
1	Front reinforcement		449.00	un
2	Radiator side air guide RH/LH@2*\$25		50.00	X
1	Support panel		609.00	X
1	Condenser		620.00	X
1	Radiator		583.00	X
1	Fan cowl assy		592.00	X
1	Duct extension		5.00	X
1	Air intake shield		8.00	X
1	Air duct		49.00	X
1	Boot lid		1298.00	bt
2	Boot lid hinge RH/LH@2*\$88		176.00	Ry
1	Boot lid logo badge		29.00	un
1	Boot lid emblem "Cerato"		25.00	un
1	Boot lid weatherstrip		90.00	un
1	Boot lid lock		101.00	un
2	Boot lid lamp RH/LH@2*\$549		1098.00	cut
1	Boot lid center garnish lamp		623.00	cut
2	Tail lamp RH/LH@2*\$609		1218.00	cut
1	Rear bumper		652.00	de
2	Rear bumper side retainer RH/LH@2*\$28		56.00	un RH X 28
1	Rear fog lamp LH		163.00	un
1	Rear fog lamp cover LH		17.00	un
2	Rear reverse sensor@2*\$62		124.00	un
1	Rear bumper lower garnish		218.00	de
1	Rear bumper lower cover LH		30.00	un
1	Rear reinforcement		287.00	un
2	Rear reinforcement beam RH/LH@2*\$59		118.00	bt
2	Rear reinforcement bracket RH/LH@2*\$8		16.00	un
2	Rear reinforcement center bracket RH/LH@2*\$6		12.00	un
1	End panel top garnish		37.00	un
1	Front fender RH/LH (Repair refer to labour)		0.00	Ry
2	Rear fender RH/LH (Repair refer to labour)		0.00	Ry
1	End panel (Repair refer to labour)		0.00	Ry
1	Floor panel (Repair refer to labour)		0.00	Ry
Part Items			14821.00	
Total:			-10%	-1482.10
				13338.90

SPECIAL NETT ITEMS

1	Bonnet insulator clips	25.00	X nn
1	Front bumper clips	35.00	nn
1	Center grille clips	25.00	nn
1	Front car plate with holder	35.00	nn
1	Radiator top garnish clips	25.00	nn
1	Coolant	50.00	X nn
1	Boot lid emblem "CC"	100.00	nn
1	Rear car plate with holder	35.00	X nn
1	Rear bumper clips	35.00	nn
1	Rear bumper lower garnish clips	30.00	nn

SN Items Total: 395.00

Total Parts 13733.90

285



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMJ1244A KIA CERATO 1.6(A) EX

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1800.00	1200 1800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1500 1800
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	40
4	Remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	100.00	200 + 100 3040
Labour Total :		3960.00	
TOTAL (PARTS & LABOUR):		17693.90	

Tanfikh 97495749/62563561

WP' 26/12/24 @ 12pm

p/p resurvey ^{before} repair, No 2nd hand part

Tanfikh @ lkkauto.wm.

09 days

8876.70

285

3040

\$12,201.70

09 days

✗

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: