

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CHUA MUI GEK
36 WOODLANDS DRIVE 16 #12-35
SINGAPORE 737772

Contact : 81288476 85180415

Hui Rong

TAX INVOICE

Repair Code : CLM18465

Date in : 23/12/2024

Vehicle Num. : SKV4553Z

Model : MERCEDES BENZ GLA180 AMG LINE EDITION AUTO

Chassis/Eng# : WDC1569422J653844/27091031903671

Parts and Labour Assesment

Description of part	Qty	Unit Price	1650 Amount
FRONT BUMPER <i>Dehid</i>	1	2150.00	2,150.00
FRONT BUMPER LH FOGLAMP GARNISH <i>new</i>	1	75.00	+ 75.00
FRONT BUMPER LH INNER BRACKET <i>could</i>	1	125.70	✓ 125.70
FRONT BUMPER LH PARKING SENSOR <i>new</i>	1	220.00	✓ 220.00
FRONT BUMPER LH SIDE RETAINER <i>new</i>	1	30.00	+ 30.00
FRONT BUMPER LOWER LID <i>cut</i>	1	700.00	✓ 700.00
FRONT BUMPER PARKING SENSOR 'O' RING <i>1 piece new</i>	4	15.00	15 60.00
FRONT BUMPER PARKING SENSOR HOLDER <i>new</i>	4	35.00	✓ 140.00
FRONT LH BEARING <i>new</i>	1	500.00	+ 500.00
FRONT LH DOOR <i>Dehid</i>	1	2330.00	2150 2,330.00
FRONT LH DOOR OUTER MOULDING <i>new</i>	1	170.00	+ 170.00
FRONT LH DOOR SIDE MIRROR ASSY <i>new</i>	1	730.00	+ 730.00
FRONT LH FENDER <i>Dehid</i>	1	1070.00	✓ 1,070.00
FRONT LH FENDER ARCH GARNISH <i>Dehid</i>	1	290.00	✓ 290.00
FRONT LH FENDER INNER SHIELD COVER <i>ton</i>	1	305.00	✓ 305.00
FRONT LH HEADLAMP <i>cut</i>	1	3130.00	✓ 3,130.00
LH ROCKER GARNISH <i>new</i>	1	3010.00	+ 3,010.00
REAR LH DOOR <i>Dehid</i>	1	2755.00	2,755.00 2440

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CHUA MUI GEK
36 WOODLANDS DRIVE 16 #12-35
SINGAPORE 737772

Contact : 81288476 85180415

TAX INVOICE

Repair Code : CLM18465

Date in : 23/12/2024

Vehicle Num. : SKV4553Z

Model : MERCEDES BENZ GLA180 AMG LINE EDITION AUTO

Chassis/Eng# : WDC1569422J653844/27091031903671

REAR LH DOOR 'TRANSPARENT' STICKER <i>New</i>	12115.70	1	85.00	✓	85.00
REAR LH FENDER ARCH GARNISH <i>New mw</i>	10904.13	1	305.00	+	305.00
Subtotal before discount					18,180.70
Percentage discount 10%					1,818.07
Sub-total 1					16,362.63
FRONT BUMPER CLIPS - SET <i>New</i>		1	50.00	✓	50.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>New</i>		1	50.00	T	50.00
FRONT LH DOOR SIDE MIRROR COVER <i>Added</i>		1	80.00	✓	80.00
FRONT LH FENDER INNER SHIELD COVER CLIPS - SET <i>mw</i>		1	30.00	✓	30.00
FRONT LH SPORT RIM <i>ct</i>	1360	1	850.00	600	850.00
LH ROCKER GARNISH CLIPS - SET <i>3 New</i>		1	50.00	+	50.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET		1	50.00	+	50.00
REAR LH SPORT RIM <i>ct</i>		1	850.00	600	850.00
Subtotal before discount					2,010.00
Percentage discount 0%					0.00
Sub-total 2					2,010.00
Parts-total					18,372.63

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CHUA MUI GEK
36 WOODLANDS DRIVE 16 #12-35
SINGAPORE 737772

Contact : 81288476 85180415

TAX INVOICE

Repair Code : CLM18465

Date in : 23/12/2024

Vehicle Num. : SKV4553Z

Model : MERCEDES BENZ GLA180 AMG LINE EDITION AUTO

Chassis/Eng# : WDC1569422J653844/27091031903671

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 80.00

120 160.00

8w 1,400.00

8w 1,000.00

X 80.00

1750

Labour Total

2,720.00

Parts & Labour Total

21,092.63

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly

2/s 23/12/24

06 Days.

Total: 14014.13

L/S: 11.2K ✓