



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:KAREN TAN

INV No. AC2503048

INV Date 19/05/2025

Reference CD/FCI24120319/Epa3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKD 7590R
Insured Veh. SH 6125S
Claim No. D24010504MFCT
Policy No. D-24101861MFCT
Accident Date 28/11/2024
Inspection Date 30/12/2024

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:KAREN TAN		Ref: CD/FCI24120319/Epa3q2(N) Date: 19/05/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6125S	Veh. Inspected	SKD 7590R
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010504MFCT	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	30/12/2024
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C 180	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2040452A644516	Colour	BLUE
Odometer	200274 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/11/2024	Inspection Date	30/12/2024
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 7590R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,523.30	1,523.30
1	REAR BUMPER CENTER CHROME	BROKEN	387.20	387.20
1	REAR BUMPER SIDE CHROME RH	BROKEN	312.70	312.70
1	REAR BUMPER SIDE CHROME L/H	BROKEN	312.70	312.70
1	REAR BUMPER SIDE RETAINER L/H	NOT NECESSARY	137.70	-
1	REAR BUMPER REINFORCEMENT	BENT	672.60	672.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	987.40	-
1	REAR SPONGE	NOT NECESSARY	243.10	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	127.30	-
1	REAR TAIL LAMP L/H	NOT NECESSARY	1,267.90	-
1	REVERSE SENSOR OUTER L/H	SHORTED	322.50	250.00
1	TAIL LAMP BRACKET L/H	BROKEN	132.80	132.80
	LESS 10% DISCOUNT		-642.72	-359.13
			5,784.48	3,232.17
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIP @\$7.50 (SN)	NECESSARY	75.00	30.00
			75.00	30.00
<u>LABOUR</u>				
	SPRAY PAINT ALL AFFECTED AREA.		900.00	200.00
	TO REMOVE AND REFIT DAMAGE PARTS TO FACILITATE REPAIR .INCLUSIVE OF THE REPAIR OF REAR END PANEL .		900.00	200.00
	RUST PROOFING TREATMENT.		90.00	30.00
			1,890.00	430.00
GRAND TOTAL			7,749.48	3,692.17



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,950.00
---	--	--	-----------------

Report Ref No. CD/FCI24120319/Epa3q2(N)

Market Value: \$65,000.00(est) less LTA Rebate: \$25,884.00(est) = Nett Value :\$39,116.00(est)

CHEN TSUE YEE
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 4)


PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R



PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SKD 7590R

