

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0945/2024/EQ
DATE : 26-Dec-24
WIP : 42703

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MRS WONG MUI KWAI
ADDRESS : 22 SPRINGSIDE CRESCENT
SINGAPORE 786160

TELEPHONE : HP +65 91688345
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800096556-06
VEHICLE NO : **SMD 7269 X**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 31/8/2018
ENGINE NO : CVK 064494
CHASSIS NO : WAUZZZF42JN015337
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Dec-24
PLACE OF ACCIDENT : SPRINGSIDE AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 7269 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	280
2	TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,750.00	500
3	TO RESPRAY LHS FRONT DOOR AND LHS SILL PANEL.	\$ 1,900.00	1100
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	✓
TOTAL LABOUR CHARGES		: \$ 4,292.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 7269 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH <i>Dented</i>	1	\$ 3,647.00	✓
2	FRONT DOOR OUTER SEAL <i>New</i>	1	\$ 275.00	✓
3	BONDING AGENT <i>?</i>	1	\$ 54.00	?
4	CLEANING SOLUTION <i>?</i>	1	\$ 92.00	?
5	APPLICATOR <i>?</i>	1	\$ 10.00	?
6	FRONT DOOR CATCH - LH <i>?</i>	1	\$ 131.00	?
7	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 1,179.00	X
8	SUNDRIES <i>?</i>		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 5,888.00	
TOTAL LABOUR CHARGES		:	\$ 4,292.00	
GRAND TOTAL		:	\$ 10,180.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lij
27/12/24

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 0 days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT